

NEW ZEN WERKZ PTE LTD

BLK 3 KAKI BUKIT RD 1 #03-04 EUNOS TECHNOLINK SINGAPORE 415935

FARISHA BTE MOHD SIKANDAR
 Blk 3 Kaki Bukit Road 1
 # 03 – 04 Eunoss Technolink
 Singapore 415935

10th June 2021

TPAIG.
Cecilia

Accident date: 09th JUNE 2021

Estimated repair cost for vehicle no: SJV5082X MITSUBISHI LANCER

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Number Plate <i>3 per new</i>		\$50.00 <i>X</i>
2	1	Rear Boot Lid Number Plate Garnish		\$115.00 <i>X</i>
3	1	Rear Tail Lamp -RH <i>cut</i>		\$385.00 <i>X</i>
4	4	Rear tail lamp clips <i>new</i>	\$8.00	\$32.00 <i>10</i>
5	2	Rear Tail Lamp Panel <i>new</i>	\$112.00	\$138.00 <i>X</i>
6	1	Rear Bumper <i>Deland</i>		\$674.00 <i>X</i>
7	2	Rear Bumper Side Bracket <i>Not use</i>	\$112.00	\$82.00 <i>X 12</i>
8	12	Rear Bumper Side Bracket Devit <i>Not use</i>	\$2.50	\$30.00 <i>X</i>
9	1	Rear Bumper Center Beam <i>best</i>		\$215.00 <i>155</i>
10	10	Rear Bumper Clips <i>new</i>	\$6.50	\$65.00 <i>30</i>
11	1	Rear Bumper Reverse Sensor <i>Dead</i>		\$300.00 <i>200(SN)</i>
12	1	raer bumper reinforcement <i>Dented</i>		\$388.00 <i>325</i>
13	1	Rear End Panel <i>Rep</i>		\$412.00 <i>X</i>
14	1	Rear End Panel Top Garnish <i>NA</i>		\$168.00 <i>X</i>

1579

Subtotal :- \$3,054.00

S-N: 200.

1421.10

Labour charges

To remove & refix cushion	\$120.00 <i>40</i>
To Remove & refix reverse sensor	\$120.00 <i>50</i>
Tuff kote	\$120.00 <i>50</i>
To check wiring	\$60.00 <i>30</i>
Panel beating	\$600.00 <i>300</i>
Spray painting	\$600.00 <i>400</i>

870

Subtotal :- \$1,620.00

Total :- \$4,674.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

total: 2991.10

L/S: 2K

OH Days