



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

Lek/Adrian

DAVE KOH SZE MENG

2 TOPAZ ROAD #02-03

SINGAPORE 327848

ESTIMATE

Repair Code : CLM16848

Date in : 14/06/2021

Vehicle Num. : ES64G

Model : TOYOTA LEXUS CT200H AUTO PREMIUM

Chassis/Eng# : JTHKD5BH702025901/2ZRR284505

*TP China
Der...*

C/T.

Contact : 96661669

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Deformed.</i>	1	960.30	✓ 960.30
REAR BUMPER CORNER BRACKET L/R <i>Not new</i>	2	88.80	X 177.60
REAR BUMPER INNER PRESSURE GAS BRACKET <i>Deformed</i>	1	1092.20	✓ 1,092.20
REAR BUMPER LH REFLECTOR <i>Cracked.</i>	1	39.30	✓ 39.30
REAR BUMPER REINFORCEMENT <i>Deformed</i>	1	536.10	✓ 536.10
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Best</i>	2	85.10	✓ 170.20
REAR BUMPER REVERSE SENSOR <i>2 pieces deformed</i>	3	490.80	650. ✓ 1,472.40
REAR BUMPER REVERSE SENSOR COVER <i>new</i>	3	28.00	✓ 84.00
REAR BUMPER REVERSE SENSOR HOLDER CLIPS <i>new</i>	3	12.10	✓ 36.30
REAR BUMPER SIDE RETAINER L/R <i>Not new</i>	2	126.10	X 252.20
REAR END PANEL <i>Dented.</i>	1	893.90	✓ 893.90
REAR END PANEL AIR VENT <i>Not new</i>	1	34.80	+ 34.80
REAR END PANEL ANTENNA SENSOR <i>cracked</i>	1	212.10	✓ 212.10
REAR END PANEL INNER TOP GARNISH <i>Deformed</i>	1	251.30	✓ 251.30
REAR LH TAILLAMP <i>cracked</i>	1	674.00	✓ 674.00
REAR TAILGATE <i>Dented.</i>	1	1806.70	✓ 1,806.70
REAR TAILGATE 'CT200H' EMBLEM	1	79.10	✓ 79.10
REAR TAILGATE 'LEXUS' EMBLEM <i>} new</i>	1	68.20	✓ 68.20

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

DAVE KOH SZE MENG

2 TOPAZ ROAD #02-03

SINGAPORE 327848

Contact : 96661669

ESTIMATE

Repair Code : CLM16848

Date in : 14/06/2021

Vehicle Num. : ES64G

Model : TOYOTA LEXUS CT200H AUTO PREMIUM

Chassis/Eng# : JTHKD5BH702025901/2ZRR284505

REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	10.00	<i>X</i>	20.00
REAR TAILGATE INNER TRIM GARNISH <i>new</i>	1	363.70	<i>X</i>	363.70
REAR TAILGATE MECHANISM LOCK <i>Demd</i>	1	467.60	<i>✓</i>	467.60
REAR TAILGATE OUTER GARNISH <i>crackd</i>	1	1104.70	<i>✓</i>	1,104.70
REAR TAILGATE OUTER GARNISH LOGO EMBLEM <i>new</i>	1	182.80	<i>✓</i>	182.80
REAR TAILGATE REFLECTOR GASKET SEAL L/R <i>new</i>	2	39.10	<i>X</i>	78.20
REAR TAILGATE REFLECTOR L/R <i>lit crackd</i>	2	472.10	<i>472.10</i>	<i>944.20</i>
REAR TAILGATE WEATHER STRIP <i>new</i>		409.30	<i>X</i>	409.30
REAR TAILGATE WINDSCREEN LOWER MOULDING <i>new</i>		38.60	<i>-</i>	38.60
REAR TAILGATE WINDSCREEN MOULDING L/R <i>new</i>	2	38.60	<i>-</i>	77.20

Subtotal before discount

12,527.00

Percentage discount 10%

1,252.70

Sub-total 1

11,274.30

REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	<i>50.00</i>
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	30.00	<i>20</i>	<i>30.00</i>
REAR LH TAILLAMP CLIPS - SET <i>new</i>	1	30.00	<i>10</i>	<i>30.00</i>
REAR TAILGATE INNER RUBBER MOULDING <i>new</i>	1	80.00	<i>20</i>	<i>80.00</i>
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	50.00	<i>X</i>	50.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

DAVE KOH SZE MENG

2 TOPAZ ROAD #02-03

SINGAPORE 327848

Contact : 96661669

ESTIMATE

Repair Code : CLM16848

Date in : 14/06/2021

Vehicle Num. : ES64G

Model : TOYOTA LEXUS CT200H AUTO PREMIUM

Chassis/Eng# : JTHKD5BH702025901/2ZRR284505

REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	160	1	50.00	20 50.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>		1	60.00	60.00
Subtotal before discount				350.00
Percentage discount 0%				0.00
Sub-total 2				350.00
Parts-total				11,624.30

LABOUR

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	3,340.00
Parts & Labour Total	14,964.30

LKK Auto Consultants hence notify

the Repairer of the following. *** This is a computer-generated document which requires no signature. ***

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 11067.03

L/S: 7K
(Nett Value)

05 Days