

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



*Hui Zhen .*

## Supplementary Estimate

GST Reg No. 19-9902271-W

**China Taiping Insurance (SG) Pte Ltd**  
105 Cecil Street  
#19-00 The Octagon  
Singapore 069534  
Attn: Motor Claims Dept  
Tel: 6389 6541 - Fax: 6224 7175

Estimate No.  
Date  
Service Advisor  
Pages  
Regn No  
Model No

PA/TP/0480/2021/KS  
21-Jun-21  
CHANG  
1 of 1 **4431**  
SMQ ~~945~~ L  
AUDI A1 SPORTBACK 1.0 TFSI

Quantity	Description	Unit Price	Amount
<b>Labours</b>			
1	TO DISMANTLE AND RENEW GEARBOX MECHATRONIC S/N	\$ 980.00	✓
<b>Parts</b>			
1	FLAP SUPPORT <i>Best</i>	\$ 77.00	✓
2	COOLANT HOSE WITH QUICK RELEASE COUPLING <i>used</i>	\$ 185.00	✓
3	COOLANT PIPE <i>used</i>	\$ 30.00	✓
4	WIRE <i>snapped</i>	\$ 63.00	✓
5	WIRE BUTT CONNECTOR <i>new</i>	\$ 21.00	✓
6	BATTERY CONSOLE <i>Broken + could</i>	\$ 125.00	✓
7	GEARBOX MECHATRONIC UNIT <i>Dented</i>	\$ 3,977.00	✓
8	ATF OIL <i>New</i>	\$ 186.00	✓
9	GEARBOX MECHATRONIC UNIT BOLTS <i>new</i>	\$ 62.00	✓
<b>GRAND TOTAL</b>		<b>\$ 5,706.00</b>	

For Premium Automobiles Pte Ltd

*Adrian Limy*  
*21/06/21*



Authorised Signature

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMO 9431 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	S/N \$ 360.00	/
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	/
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	/
4	TO RENEW AIR INTAKE MANIFOLD AND OTHER ENGINE COMPONENTS.	S/N \$ 980.00	✓
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET		
5	BOTH FRONT FENDER AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO REPAIR BOTH FRONT FENDER TOP SUPPORTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL REMOVED PARTS.	7 x 700 \$ 6,300.00	4900
6	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, HINGES, BOTH FRONT FENDER TOP SUPPORTS, BOTH AND BOTH FRONT DOOR. (Green - 1) (RH)	5 x 700 + 100 + 50 \$ 6,800.00	3650
7	TO REMOVE AND REINSTALL FRONT BUMPER LOWER SPOILER.	S/N \$ 280.00	/
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 16,812.00</b>	

Car-in

15/6/21

wip: 30191

Kiam/Kean g



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

CT - store

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 9431 L

10 days

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / BR	1	\$	1,634.00	
2	FRONT BUMPER FIXING PARTS	1	\$	137.00	
3	FRONT BUMPER SPOILER LH / RH	2	\$	200.00	
4	FRONT BUMPER AIR GUIDE GRILLE / RH BR 1	1	\$	422.00	
5	FRONT BUMPER GRILLER - CENTER	1	\$	196.00	
6	FRONT BUMPER CLOSING ELEMENT	1	\$	167.00	
7	RADIATOR GRILLE / BR	1	\$	926.00	
8	FRONT BUMPER TOP MOUNT BRACKET	1	\$	161.00	✓
9	FRONT BUMPER REINFORCEMENT BEAM	1	\$	723.00	✓
10	FRONT FOAM FILLER PIECE / BR	1	\$	118.00	
11	FRONT BUMPER TOP COVER / BR	1	\$	123.00	
12	FRONT BUMPER GUIDE SECTION LH / RH	2	\$	214.00	✓
13	FRONT BUMPER GUIDE PROFILE LH / RH	2	\$	72.00	36.
14	"CAUTION" SIGN STICKER	1	\$	14.00	
15	"AC" STICKER	1	\$	19.00	
16	HORN LH	1	\$	137.00	
17	HORN RH	1	\$	130.00	
18	HORN BRACKET LH	1	\$	41.00	
19	HORN BRACKET RH	2	\$	31.00	
20	FRONT FENDER LH / RH / OD	2	\$	1,956.00	
SUB TOTAL SPARE PARTS			:	\$	7,421.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : HORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 9431 L**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET LH / RH <i>BT</i>	2	\$	72.00
22	FRONT FENDER BRACKET LH / RH	2	\$	28.00
23	FRONT FENDER BRACKET LH / RH	2	\$	116.00
24	FRONT FENDER BRACKET LH / RH <i>Bent</i>	2	\$	108.00 ✓
25	BONNET <i>OK</i>	1	\$	2,282.00
26	BONNET HINGE LH / RH <i>BT</i>	2	\$	124.00
27	BONNET STRIKER LH / RH <i>BT</i>	2	\$	198.00
28	BONNET ATTACHMENT PART <i>X</i>	1		TBC
29	BONNET IMPACT PROTECTION LH / RH <i>APC</i>	2	\$	62.00
30	BONNET IMPACT PROTECTION CENTER <i>APC APC</i>	1	\$	31.00
31	BONNET SOUND ABSORBER <i>CR4</i>	1	\$	219.00
32	BONNET GASKET <i>APC</i>	1	\$	93.00
33	BONNET BOWDEN CABLE CENTER <i>?</i>	1	\$	84.00
34	BONNET BOWDEN CABLE LH / RH <i>?</i>	2	\$	58.00
35	BONNET LOCK WITH MICRO-SWITCH LH / RH <i>?</i>	2	\$	427.00
36	BONNET LOCK WITH MICRO-SWITCH CONNECTOR LH / RH <i>?</i>	2	\$	26.00
37	BONNET RELEASE LEVER <i>?</i>	1	\$	14.00
38	BONNET RELEASE CABLE COVER <i>?</i>	1	\$	10.00
39	BONNET RELEASE CABLE <i>?</i>	1	\$	47.00
40	PLENUM CHAMBER COVER <i>X</i>	1		TBC
<b>SUBTOTAL SPARE PARTS</b>		:	\$	<b>3,999.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 9431 L**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LED HEADLIGHT LH / RH ✓ <i>OR</i>	2	\$ 4,288.00	$\times 2 = \$8,576$
42	LED HEAT SINK LH / RH ?	2	\$ 1,432.00	
43	LED HEADLIGHT POWER MODULE LH / RH ?	2	\$ 1,516.00	
44	LED HEADLIGHT BREATHER HOSE LH / RH ?	2	\$ 60.00	
45	LED HEADLIGHT LIFT CYLINDER LH / RH ?	2	\$ 284.00	
46	LIFT CYLINDER HOSE ?	1	\$ 59.00	
47	WINDSCREEN WASHER PUMP ?	1	\$ 125.00	
48	WASH WATER RESERVOIR ✓ <i>CR4</i>	1	\$ 189.00	
49	WASH WATER RESERVOIR NECK ?	1	\$ 58.00	
50	LOCK CARRIER ✓ <i>DD</i>	1	\$ 152.00	$\$1,272$
51	LOCK CARRIER BRACE LH / RH UPPER ✓ <i>DD</i>	2	\$ 152.00	
52	A/C CONDENSOR ✓ <i>DD</i>	1	\$ 503.00	
53	A/C REFRIGERANT LINE ✓ <i>ut</i>	1	\$ 340.00	✓
54	A/C REFRIGERANT HOSE ?	1	\$ 261.00	
55	OUTSIDE TEMPERATURE SENSOR ?	1	\$ 59.00	
56	ADDITIONAL RADIATOR ✓ <i>DD</i>	1	\$ 931.00	
57	RADIATOR ✓ <i>DD</i>	1	\$ 931.00	
58	RADIATOR AIR GUIDE LH / RH ✓ <i>BR</i>	1	\$ 76.00	
59	RADIATOR SEALING STRIP LH / RH ✓ <i>emld</i>	2	\$ 62.00	
60	RADIATOR RUBBER BUSH LH / RH UPPER ✓ <i>Dmg d</i>	2	\$ 82.00	
<b>SUBTOTAL SPARE PARTS</b>			\$ <del>15,560.00</del>	<b>15,848</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 9431 L**

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR RUBBER BUSH LH / RH LOWER ?	2	\$ 19.00	
62	RADIATOR COOLANT ✓	6	\$ 269.00	
63	RADIATOR FAN ✓	2	\$ 1,199.00	
64	AIR INTAKE AIR GUIDE ✓	1	\$ 53.00	
65	AIR INTAKE AIR GUIDE ✓	1	\$ 42.00	
66	INTAKE MANIFOLD PIPE ?	1	\$ 139.00	
67	AIR FILTER ?	1	\$ 2,745.00	
68	WATER DRAINAGE HOSE ?	1	\$ 33.00	
69	INTAKE MANIFOLD ? Damd. ✓	1	\$ 666.00	
70	INTAKE MANIFOLD SEAL ?	1	\$ 14.00	
71	INTAKE THROTTLE VALVE ?	1	\$ 754.00	
72	INTAKE THROTTLE VALVE SEAL ?	1	\$ 14.00	
73	INTAKE THROTTLE VALVE O-RING ?	1	\$ 18.00	
74	RETAINING BAR ?	1	\$ 15.00	
75	FRONT WHEEL HOUSING LINER LH / RH ?	2	TBC	
76	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	2	\$ 69.00	
77	FRONT NO PLATE WITH HOLDER ✓	S/N	\$ 100.00	
78	SUNDRIES ?	1	\$ 300.00	
TOTAL SPARE PARTS		:	\$ <del>29,429.00</del> \$33,717	
TOTAL LABOUR CHARGES		:	\$ 16,812.00	
GRAND TOTAL		:	\$ <del>46,241.00</del> \$50,529	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

Photo.  
Required