

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534
Attn: Motor Claims Dept
Tel: 6389 6541 - Fax: 6224 7175

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/0480/2021/KS
21-Jun-21
CHANG
1 of 1 **431**
SMQ ~~946~~ L
AUDI A1 SPORTBACK 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO DISMANTLE AND RENEW GEARBOX MECHATRONIC S/N	\$ 980.00	✓
Parts			
1	FLAP SUPPORT <i>Bent</i>	\$ 77.00	✓ 76.20
2	COOLANT HOSE WITH QUICK RELEASE COUPLING <i>used</i>	\$ 185.00	✓ 185
3	COOLANT PIPE <i>Dented</i>	\$ 30.00	✓ 29.60
4	WIRE <i>sapped</i>	\$ 63.00	✓ 62.70
5	WIRE BUTT CONNECTOR <i>new</i>	\$ 21.00	✓ 20.40
6	BATTERY CONSOLE <i>Broken + Cracked</i>	\$ 125.00	✓ 129
7	GEARBOX MECHATRONIC UNIT <i>Dented</i>	\$ 3,977.00	✓ 3977
8	ATF OIL <i>New</i>	\$ 186.00	✓ 185.70
9	GEARBOX MECHATRONIC UNIT BOLTS <i>new</i>	\$ 62.00	✓ 52.80
GRAND TOTAL		\$ 5,706.00	

For Premium Automobiles Pte Ltd

Adrian Lim
21/06/21



Authorised Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

E-MAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMQ 9431 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR. HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	✓
4	TO RENEW AIR INTAKE MANIFOLD AND OTHER ENGINE COMPONENTS.	S/N \$ 980.00	✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET BOTH FRONT FENDER AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO REPAIR BOTH FRONT FENDER TOP SUPPORTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL REMOVED PARTS	7 x 700 \$ 6,300.00	4900 ✓
6	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, HINGES, BOTH FRONT FENDER TOP SUPPORTS, BOTH AND BOTH FRONT DOOR. <i>Green - 1 (RH)</i>	5 x 700 + 100 + 50 \$ 6,800.00	3650 ✓
7	TO REMOVE AND REINSTALL FRONT BUMPER LOWER SPOILER.	S/N \$ 280.00	✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 16,812.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam / Keong



CT - Store

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 9431 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / BR	1	\$	1,634.00	1634
2	FRONT BUMPER FIXING PARTS ? x nn	1	\$	137.00	
3	FRONT BUMPER SPOILER LH / RH ? x nn	2	\$	200.00	
4	FRONT BUMPER AIR GUIDE GRILLE LH / RH BR 1/2	1	\$	422.00	210.50
5	FRONT BUMPER GRILLER - CENTER ? x nn	1	\$	196.00	
6	FRONT BUMPER CLOSING ELEMENT ? x nn	1	\$	167.00	
7	RADIATOR GRILLE / BR	1	\$	926.00	926
8	FRONT BUMPER TOP MOUNT BRACKET encl'd Best	1	\$	161.00	160.50
9	FRONT BUMPER REINFORCEMENT BEAM	1	\$	723.00	723
10	FRONT FOAM FILLER PIECE / BR	1	\$	118.00	117.50
11	FRONT BUMPER TOP COVER / BR	1	\$	123.00	122.50
12	FRONT BUMPER GUIDE SECTION LH / RH encl'd	2	\$	214.00	214
13	FRONT BUMPER GUIDE PROFILE LH / RH RH encl'd	1	\$	72.00	36.35.40
14	"CAUTION" SIGN STICKER	1	\$	14.00	13.60
15	"AC" STICKER	1	\$	19.00	18.50
16	HORN LH ? x nn	1	\$	137.00	
17	HORN RH ? x nn	1	\$	130.00	
18	HORN BRACKET LH ? x nn	1	\$	41.00	
19	HORN BRACKET RH ? x nn	2	\$	31.00	
20	FRONT FENDER LH / RH / DD	2	\$	1,956.00	1956
SUB TOTAL SPARE PARTS		:	\$	7,421.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

10 days

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5MQ 9431 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET LH / RH <i>BT</i>	2	\$ 72.00	<i>72.60</i>
22	FRONT FENDER BRACKET LH / RH <i>x nn</i>	2	\$ 28.00	
23	FRONT FENDER BRACKET LH / RH <i>x nn</i>	2	\$ 116.00	
24	FRONT FENDER BRACKET LH / RH <i>Best</i>	2	\$ 108.00	<i>106.80</i>
25	BONNET <i>nn</i>	1	\$ 2,282.00	<i>2282</i>
26	BONNET HINGE LH / RH <i>BT</i>	2	\$ 124.00	<i>122.20</i>
27	BONNET STRIKER LH / RH <i>BT</i>	2	\$ 198.00	<i>197.80</i>
28	BONNET ATTACHMENT PART <i>x nn</i>	1	TBC	
29	BONNET IMPACT PROTECTION LH / RH <i>nc</i>	2	\$ 62.00	<i>60.60</i>
30	BONNET IMPACT PROTECTION CENTER <i>nc nc</i>	1	\$ 31.00	<i>30.30</i>
31	BONNET SOUND ABSORBER <i>CR4</i>	1	\$ 219.00	<i>219</i>
32	BONNET GASKET <i>nc</i>	1	\$ 93.00	<i>92.80</i>
33	BONNET BOWDEN CABLE CENTER <i>x nn</i>	1	\$ 84.00	
34	BONNET BOWDEN CABLE LH / RH <i>x nn</i>	2	\$ 58.00	
35	BONNET LOCK WITH MICRO-SWITCH LH / RH <i>x nn</i>	2	\$ 427.00	
36	BONNET LOCK WITH MICRO-SWITCH CONNECTOR LH / RH <i>x nn</i>	2	\$ 26.00	
37	BONNET RELEASE LEVER <i>x nn</i>	1	\$ 14.00	
38	BONNET RELEASE CABLE COVER <i>x nn</i>	1	\$ 10.00	
39	BONNET RELEASE CABLE <i>x nn</i>	1	\$ 47.00	
40	PLENUM CHAMBER COVER <i>x nn</i>	1	TBC	
SUBTOTAL SPARE PARTS			\$	3,999.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 9431 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LED HEADLIGHT LH / RH <i>BR</i>	2	\$ 4,288.00	<i>x 2 = \$ 8,576</i>
42	LED HEAT SINK LH / RH <i>? x nn</i>	2	\$ 1,432.00	
43	LED HEADLIGHT POWER MODULE LH / RH <i>? x nn</i>	2	\$ 1,516.00	
44	LED HEADLIGHT BREATHER HOSE LH / RH <i>? x nn</i>	2	\$ 60.00	
45	LED HEADLIGHT LIFT CYLINDER LH / RH <i>? x nn</i>	2	\$ 284.00	
46	LIFT CYLINDER HOSE <i>? x nn</i>	1	\$ 59.00	
47	WINDSCREEN WASHER PUMP <i>? x nn</i>	1	\$ 125.00	
48	WASH WATER RESERVOIR <i>CRY</i>	1	\$ 189.00	<i>189</i>
49	WASH WATER RESERVOIR NECK <i>? x nn</i>	1	\$ 58.00	
50	LOCK CARRIER <i>DD</i>	1	\$ 152.00	<i>\$ 1,272</i>
51	LOCK CARRIER BRACE LH / RH UPPER <i>DD</i>	2	\$ 152.00	<i>151</i>
52	A/C CONDENSOR <i>DD</i>	1	\$ 503.00	<i>503</i>
53	A/C REFRIGERANT LINE <i>ut</i>	1	\$ 340.00	<i>339.50</i>
54	A/C REFRIGERANT HOSE <i>? x nn</i>	1	\$ 261.00	
55	OUTSIDE TEMPERATURE SENSOR <i>? x nn</i>	1	\$ 59.00	
56	ADDITIONAL RADIATOR <i>DD</i>	1	\$ 931.00	<i>930.50</i>
57	RADIATOR <i>DD</i>	1	\$ 931.00	<i>930.50</i>
58	RADIATOR AIR GUIDE LH / RH <i>BR</i>	2	\$ 76.00	<i>74.40</i>
59	RADIATOR SEALING STRIP LH / RH <i>could</i>	2	\$ 62.00	<i>60.40</i>
60	RADIATOR RUBBER BUSH LH / RH UPPER <i>Day d</i>	2	\$ 82.00	<i>81.60</i>
SUBTOTAL SPARE PARTS			\$ 11,560.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 9431 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR RUBBER BUSH LH / RH LOWER ? x nn	2	\$ 19.00	
62	RADIATOR COOLANT / nec	6	\$ 269.00	268.20
63	RADIATOR FAN / BR	2	\$ 1,199.00	1199
64	AIR INTAKE AIR GUIDE / BR	1	\$ 53.00	52.30
65	AIR INTAKE AIR GUIDE / BR	1	\$ 42.00	41.20
66	INTAKE MANIFOLD PIPE ? + nn	1	\$ 139.00	
67	AIR FILTER ? x nn	1	\$ 2,745.00	
68	WATER DRAINAGE HOSE ? x nn	1	\$ 33.00	
69	INTAKE MANIFOLD Dem'd. BR	1	\$ 666.00	666.50
70	INTAKE MANIFOLD SEAL ? x nn	1	\$ 14.00	
71	INTAKE THROTTLE VALVE ? + nn	1	\$ 754.00	
72	INTAKE THROTTLE VALVE SEAL ? x nn	1	\$ 14.00	
73	INTAKE THROTTLE VALVE O- RING ? x nn	1	\$ 18.00	
74	RETAINING BAR ? + nn	1	\$ 15.00	
75	FRONT WHEEL HOUSING LINER LH / RH ? x nn	2	TBC	
76	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	2	\$ x nn 69.00	
77	FRONT NO PLATE WITH HOLDER / BR	S/N	\$ 100.00	100
78	SUNDRIES ? - nec	1	\$ 300.00	214.30
TOTAL SPARE PARTS			\$ 29,429.00	
TOTAL LABOUR CHARGES			\$ 16,812.00	
GRAND TOTAL			\$ 46,241.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

Photo.
required