

CS

ASS. REC. BY:

REF:

MSG 21006711/T.953

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1001437475Claims No. 258313

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$9500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBQ 551SK Yr Regn: 23/10/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Sniper c.c. 150Colour Dark Green A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3UG0740K0153242

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90R17R: 120/70R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 14/6/21 01/15pmSurvey held at United Cycle

Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
01/12/22	Submit final fig \$758.20, 3 days.
	(ACCORDING TO TAUFIKH, WKSP DID NOT ACCEPT OUR OFFER AND PASS THE CASE TO THIER LAWYER).
	(Red \$344.80, 31%)

Date/Time, File Pass to?

01/12
1) 25/06 typist

Date/Time, File Return to?

2)

Rep. Format: MER-PRO

Lump Sum / L.B.I. (\$ _____)

☒ : Preli. Report
☐ : Final Report
Days Of Repair: 3Resurvey No. of Trip: 2
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S. + RS. \$ _____

Photos

Others

TOTAL



UNITED CYCLES LLP

25, Kaki Bukit Road 4 #01-23/24/25

Synergy @ KB Singapore 417800

Tel: 6345 9060 Fax: 6345 2356

Email: united_cycles@yahoo.com

LLP Reg No: T12LL2150G

Date: 22 June 2021

LKK Auto Consultants Pte Ltd

Dear Sirs,

RE: ESTIMATE REPAIR COST FOR FBQ5515K

1) Front Fender	\$ 50.00 cut ✓
2) Handle Balancer	\$ 15.00 mis ✓
3) Brake Lever	\$ 18.00 cut ✓
4) Mirror Sets	\$ 30.00 cut ✓
5) Side Body Cover (L/H)	\$ 80.00 cut ✓
6) Side Inner Cover (L/H)	\$ 25.00 cut ✓
7) Front Center Cowling	\$ 60.00 cut ✓
8) Front Center Cover (Inner)	\$ 50.00 de ✓
9) Exhaust Protector Cover	\$ 45.00 cut ✓
10) Exhaust Cover (End)	\$ 25.00 cut ✓
11) Basket (Center)	\$ 25.00 X m ✓
12) Front Fork Alignment	\$ 200.00 120 ✓
13) Labour Charges	\$ 400.00 200 ✓
14) Towing x 2 Ways	\$ 80.00 ✓

TOTAL REPAIR COST

\$ 1,103.00

398
10% - 358.20
400
\$ 758.20

Yours faithfully,
United Cycles LLP



Tanpin 97495749
wp' 16/6/21 @ 11:57pm
tanpin@lkkauto.com
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: