

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref: CS/AIG21006712/T1vf3e2		
78 SHENTON WAY #09-16		Date: 02/09/2021		
AIG BUILDING				
SINGAPORE 079120		Code: AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	EZ 9933C	Veh. Inspected	SBS 3280P	
Policy No.	1900079880	Coverage (\$)	0.00	
Claim No.	0770209061SG	Excess (\$)	0.00	
Assign From	DIVYASHNI SUBRAMANIAM	Assign Date	15/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	YV3S4P926DA160721	Colour		
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/06/2021	Inspection Date	17/06/2021	
Survey held at	SBS TRANSIT LTD (Branch) BEDOK NORTH DEPOT 1470 BEDOK NORTH AVE 4 SINGAPORE 489946			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				