

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 15.06.2021

Accident Date : 10.06.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Renault Fluence" Reg. No. SKU8783E Claiming Against Your Insured Reg. No. SKA2629M			
			2015
1pc	Boot		✓ 1,500.00 DDV
1pc	Boot Emblem		97.00 110.00 NECV
1pc	Boot Lock		267.00 320.00 JMV
1pc	Boot Weatherstrip		209.00 365.00 TN
1pc	Boot Trim Board		360.00 420.00 TN ✓
11pcs	Boot Trim Board Clips	8.00	30.00 88.00 NECV
1pc	Boot Lamp RH		270.00 330.00 BRV
1pc	Boot Lamp Gasket RH		✓ 35.00 NECV
1pc	Rear Bumper		1020.00 1,350.00 BRV
11pcs	Rear Bumper Clips	7.00	30.00 70.00 NECV
2pcs	Rear Bumper Brackets	65.00 145.00	130.00 290.00 BRV/NEC
1pc	Rear Bumper Sponge		230.00 NSX
1pc	Rear Bumper Reinforcement		✓ 580.00 BRV
1pc	Rear Bumper Core		365.00 NSX
1pc	Rear Bumper Side Core RH		95.00 195.00 BRV
2pcs	Rear Bumper Sensors	284.00	200.00 568.00 SCV
4pcs	Rear Bumper Sensor Holders	35.00	✓ 140.00 NECV
1pc	Rear Bumper Sensor Wiring Harness		200.00 350.00 SCV
1pc	Rear Bumper Reflector RH		150.00 NDV
2pcs	Rear Bumper Top Retainers	122.00	244.00 NSX
1pc	Rear Bumper Corner Retainer RH		115.00 NSX
1pc	Rear Bumper Inner Boot Sensor		200.00 260.00 BRV
1pc	Rear Bumper Top Beam		360.00 NSX
5pcs	Rear Bumper Top Beam Rivets	14.50	✓ 72.50 NECV
1pc	Taillamp RH		280.00 410.00 BRV
1pc	Taillamp Gasket		30.00 NSX
1pc	Taillamp Side Garnish Cover RH		✓ 160.00 BRV
1pc	End Panel		487.00 720.00 DDV
1pc	End Panel Garnish		225.00 320.00 BRV
1pc	Rear Styrofoam Storage Tray		310.00 460.00 BRV
1pc	Rear Fender Trim Board		465.00 535.00 TN ✓
1pc	Spare Tyre Top Board		390.00 490.00 DDV
1pc	Spare Tyre Panel		1078.88 1,150.00 DDV
Less 20%		8831.38	12,782.50
		1766.28	2,556.50
		7065.10	10,226.00
		C/F	10,226.00

@ 20%

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: _____

Date: 15.06.2021

Accident Date : 10.06.2021

sku 8783E

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Renault Fluence" Reg. No. SKU8783E Claiming Against Your Insured Reg. No. SKA2629M		
		B/F	10,226.00
	To Dismantle / Transfer Boot Fittings / Ancillary Accessories	80.00 ✓	120.00 ✓
	To Conduct Electrical Check, Replace Reverse Sensors, Wiring Harness & Reprogram System	60.00 ✓	120.00 ✓
	To Dismantle / Refit Trunk Compartment Boards & Trims		120.00 RPTX
	To Supply Rear Panel Body Sealant	40.00 ✓	100.00 ✓
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel	80.00 ✓	150.00 ✓
	Labour Charge - Panel Beating, Repairing Of Boot Hinge, Rear Chassis Member, Floor Panel, Rear O/S Fender etc. Cnt, Weld End Panel, Spare Tyre Panel and Parts Replacement	1000.00 ✓	1,600.00 ✓
	To Respray Affected Areas (Boot, Rear Bumper, End Panel, Spare Tyre Panel, Taillamp Panel, Rear Fender RH)	800.00 ✓	1,650.00 ✓
		Total :	<u>14,086.00</u>
		2060.00	
		Parts	7865.10
		SN	-
		Labour	2060.00
			9125.10
		@20%	1825.02
			7300.08
Survey	Resurvey	Lump sum repair	
16/6/2021	17/6/2021	Repair days 8	
1415 hr	1439 hrs.		
TGim	TGim		
lin			
97361577		cor recommended	
		45 7,300/2	
		TGim lin	
		21/6/2021	