

CARPORT AUTO SERVICE

BLK 3, PIONEER ROAD NORTH

#01-24

SINGAPORE 628457

H/P 6268-5390

FAX: 6265-1528

GST Reg No: MX_0373978-EO

M/s T.O.P Design & Engineering Pte Ltd
c/o Blk 3 Pioneer Road North
#01-24
Singapore 628457

Date: 01 June 2021

FINAL REPAIR COSTS

VEHICLE NO. GBC 6209 L (TOYOTA DYNA)

Repair costs of vehicle no **GBC 6209 L** as per the surveyor's

Report Constant Appraiser Services

dated 04 June 2021 (Lump Sum) **S\$4,100.00**

7% GST: S\$ 287.00

Total: S\$4,387.00

***SINGAPORE DOLLARS: FOUR THOUSAND THREE HUNDRED AND EIGHTY
SEVEN DOLLARS ONLY***