



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref: CS3/GAI21006115/R1vf3e2-1

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date: 25/06/2021

Code: GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 4117B	Veh. Inspected	GBC 6209L
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004011	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	16/06/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA 150 M	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTFAT35Y70K202275	Colour	GREY
Odometer	553058 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	FALKEN	7 mm
L/H Front Tyre	195 R15C	FALKEN	7 mm
R/H Rear Tyre	155 R12C (D)	FALKEN	5/5 mm
L/H Rear Tyre	155 R12C (D)	FALKEN	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/05/2021	Inspection Date	27/05/2021
Survey held at	CARPORT AUTO SERVICE BLK 3 PIONEER ROAD NORTH #01-24 SINGAPORE 628457		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------