



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /NG ZHI QIN Reg No/Reg Date SMH5788G*KC17/ 25/03/201 Date In/Mileage 15/06/2021/ 0 Chassis No KNAF3416MK5027530 Engine No G4FGJH716098 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	16/06/2021/ 08:50	QUK	282 / Kevin Leong	34720
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, SUPPORT, FRT RH DOOR, BONNET & AFFECTED AREA REPAIR ON REAR RH DOOR, BOTH FRT FENDER & BOTH FRT BODY CHASSIS		2 X 400			800 2800.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER, FRT RH DOOR, REAR RH DOOR & BOTH FRT CHASSIS		3 X 350			1050 2800.00
E PNT88000 TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL					120.00
M SUNDRY PERFORM RUST PREVENTION					40 120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00
M SUNDRY SUNDRIES					20 50.00
M LAMP ASSY-HEAD, LH / CUT		1.00	1219.00	20.00	975.20
M CARRIER ASSY-FRONT END MODULE		1.00	675.00	20.00	540.00
M BEAM COMPLETE-FR BUMPER		1.00	497.00	20.00	397.60
M PANEL ASSY-FRONT DOOR, RH		1.00	1277.00	20.00	1021.60
M MOULDING ASSY-FRT DR FRAME, RH		1.00	37.00	20.00	29.60
M W/STRIP ASSY-FR DR BELT O/S RH		1.00	64.00	20.00	51.20
M W/STRIP ASSY-FR DR SIDE RH		1.00	102.00	20.00	81.60
M HANDLE ASSY-DOOR OUTSIDE, RH		1.00	164.00	20.00	131.20
M GUARD ASSY-FRONT WHEEL, RH		1.00	95.00	20.00	76.00
M ORNAMENT-KIA NO.115		1.00	32.00	20.00	25.60
M COVER-FR BUMPER		1.00	633.00	20.00	506.40
M GRILLE ASSY-RADIATOR		1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE		1.00	38.00	20.00	30.40
M GRILLE-FRONT BUMPER		1.00	262.00	20.00	209.60
M LAMP ASSY-FRONT FOG, LH		1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER, LH		1.00	36.00	20.00	28.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /NG ZHI QIN Reg No/Reg Date SMH5788G*KC17/ 25/03/201 Date In/Mileage 15/06/2021/ 0 Chassis No KNAF3416MK5027530 Engine No G4FGJH716098 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	16/06/2021/ 08:50	QUK	282 / Kevin Leong	34720

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LAMP ASSY-SIDE REPEATER, LH	1.00	143.00	20.00	114.40
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20
M AIR DUCT-FR BUMPER, LH	1.00	14.00	20.00	11.20
M STIFFNER-FR BPR LWR	1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
M PANEL ASSY-HOOD X	1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD, RH X	1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD, LH X	1.00	43.00	20.00	34.40

Estimate

Steve (LKK) OD- NM AL

EXCIS- ?

P/P

My BL dy

6 # dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by

Signature:
Date:

7% GST on **12,221.60** **855.51**

Total Payable 13,077.11

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.