



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2107634

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/11/2021
Reference CC6/CTI21006728/Kes3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLM 1263R

Insured Veh. SKK 1511Y

Claim No. SNM21D203394/C02

Policy No.

Accident Date 12/06/2021

Inspection Date 18/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21006728/Kes3q2 Date: 08/11/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKK 1511Y	Veh. Inspected	SLM 1263R
	Policy No.		Coverage (\$)	0.00
	Claim No.	SNM21D203394/C02	Excess (\$)	0.00
	Assign From		Assign Date	18/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JF1SJGK85HG086168	Colour	METALLIC DARK GREY
	Odometer	89199 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	PIRELLI	7 mm
	L/H Front Tyre	235/55 R18	PIRELLI	7 mm
	R/H Rear Tyre	235/55 R18	PIRELLI	8 mm
	L/H Rear Tyre	235/55 R18	PIRELLI	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/06/2021	Inspection Date	18/06/2021
	Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 1263R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BENT / CRACKED	550.00	550.00
1	REAR BUMPER REINFORCEMENT	BENT	320.00	320.00
1	REAR BUMPER TOW COVER	SERVICEABLE	20.00	-
2	REAR BUMPER RETAINER @\$20.00	SERVICEABLE	40.00	-
10	REAR BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
2	REAR BUMPER REFLECTOR @\$64.00	SERVICEABLE	128.00	-
1	REAR END PANEL	BENT	488.00	488.00
1	REAR END PANEL GARNISH	SERVICEABLE	80.00	-
1	REAR SPARE TYRE PANEL SPONGE	SERVICEABLE	158.00	-
1	REAR SPARE TYRE PANEL	BENT	632.00	632.00
1	TAILGATE	BENT	1,072.80	1,072.80
1	TAILGATE RUBBER	SERVICEABLE	140.00	-
1	TAILGATE EMBLEM	NECESSARY	88.00	88.00
1	TAILGATE SUBARU EMBLEM	NECESSARY	82.00	82.00
1	TAILGATE FORESTER XT EMBLEM	NECESSARY	82.00	82.00
1	REAR WINDSCREEN MOULDING	NECESSARY	150.00	150.00
2	REAR EXHAUST SILENCER BOX @\$670.00	N/S TO REPAIR SEE LABOUR / O/S BENT	1,340.00	670.00
4	REAR EXHAUST MOUNTING @\$20.00	SERVICEABLE	80.00	-
1	TAILGATE OUTER GARNISH	MTG CRACKED	175.00	175.00
	LESS 20% DISCOUNT		-1,132.16	-868.96
			4,528.64	3,475.84
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER SENSOR (SN)	DENTED	280.00	200.00
1	REAR WIND SCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			320.00	240.00
<u>LABOUR</u>				
	TO PUTTY & SPRAY PAINT.		1,000.00	800.00
	TO TRANSFER TAIL GATE FITTING.		80.00	60.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS .		100.00	100.00

Report Ref No. CC6/CTI21006728/Kes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE REAR EXHAUST SILENCER BOX .		120.00	60.00
	TO ANTI RUST .		120.00	80.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER BOX N/S .		1,000.00	900.00
			2,420.00	2,000.00
GRAND TOTAL			7,268.64	5,715.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,550.00

Report Ref No. CC6/CTI21006728/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 1263R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 1263R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 1263R

RE-INSPECTION

