

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHB7535Y

AAD2106-031

Not Notbaik
Recovery B4 paint

8 2696.65

| | | |
|-----------------------|-------------|-------------------|
| Vehicle No.: | | SHB7535Y |
| Chassis No.: | | JTDKB3FU103077070 |
| Vehicle Make: | | TOYOTA |
| Vehicle Model: | 15 JUN 2021 | PRIUS |
| Date of Accident : | | 08/06/2021 |
| Third Party Insurer : | | TOKIO |
| Date of Registration: | | 04/12/2018 |

| PART | LIST | |
|--|--------------------|-----------------|
| 1 PANEL SUB-ASSY, FRONT DOOR, RH | \$ K | 1,300.70 |
| 1 GARNISH, DOOR FRAME, RH | \$ P _h | 13.10 |
| 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH | \$ P _h | 238.30 |
| 1 HINGE ASSY, FRONT DOOR, LOWER RH | \$ P _h | 110.60 |
| 1 HINGE ASSY, FRONT DOOR, UPPER RH | \$ K | 97.50 |
| 1 TAPE, BLACK OUT, NO.1 FRT RH | \$ U _n | 13.30 |
| 1 TAPE, BLACK OUT, NO.2 FRT RH | \$ U _n | 43.50 |
| 1 TAPE, BLACK OUT, NO.3 FRT RH | \$ U _n | 26.30 |
| 1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH | \$ P _h | 926.00 |
| 1 COVER, FRONT BUMPER | \$ P _h | 516.00 |
| 1 FRONT BUMPER SIDE RETAINER RH | \$ P _h | 80.10 |
| 1 JAR ASSY, WINDSHIELD WASHER | \$ P _h | 219.10 |
| 1 FENDER SUB-ASSY, FRONT RH | \$ B _y | 977.80 ✓ |
| 1 LINER, FRONT FENDER, RH | \$ D _{it} | 206.70 ✓ |
| 1 FRONT FENDER EMBLEM RH | \$ U _n | 54.60 ✓ |
| 1 MOULDING ASSY, BODY ROCKER PANEL, RH | \$ P _h | 594.80 X |
| TOTAL | \$ | 5,418.40 |
| 25% | \$ | 1,354.60 |
| | \$ | 4,063.80 |

Special Nett

| | | |
|---------------------------------------|-------------------|-----------------|
| 2 FENDER LINER CLIP | \$ U _n | 75.00 ✓ |
| 1 RIM <i>P17</i> <i>1555-10 -725f</i> | \$ U _n | 1,879.40 ✓ |
| 1 TYRE | \$ P _h | 300.00 X |
| 1 CLIP(FOR FRONT DOOR TRIM BOARD) | \$ U _n | 65.00 X |
| 1 CLIP(FOR REAR DOOR TRIM BOARD) | \$ U _n | 65.00 X |
| 1 FRONT DOOR STICKER "TRANS-CAB" | \$ U _n | 100.00 X |
| TOTAL | \$ | 2,484.40 |

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7535Y

AAD2106-035

TOTAL PARTS \$ 6,548.20

LABOUR

| | | | |
|---|-----------|-----------------|------|
| To Rust-Proofing and apply undercoat Of The Affected Areas. | \$ | 250.00 | 30% |
| Putty And Spray Painting Of The Affected Portion. | \$ | 1,800.00 | 220% |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | 380.00 | X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 | 10% |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 1,800.00 | 200% |
| To check steering geometry and computer wheel alignment | \$ | 220.00 | 60% |
| To transfer of rear fender panel fittings, attachment and perform water seepage test. | \$ | 170.00 | X |
| TOTAL | \$ | 4,790.00 | |

Over All Total \$ 11,338.20

(PART-BY-PART) Repair Days

10-Days

2 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: