



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STAR AUTO VENTURES (ASIA) PTE LTD BLK 176 SIN MING DRIVE #04-13 SIN MING AUTOCARE SINGAPORE 575721		Ref: CI/TP21006730/Kqe2 Date: 24/06/2021 Code: TP134	
1. Policy Particulars :- INVESTIGATION CASE			
Insured Veh.		Veh. Inspected	WBA7T22060CE22268
Policy No.		Coverage (\$)	0.00
Claim No.	WBA7T22060CE22268	Excess (\$)	0.00
Assign From		Assign Date	11/06/2021
2. Vehicle Particulars & Condition			
Make & Model	BMW 740LI (A)	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WBA7T22060CE22268	Colour	METALLIC BLACK
Odometer	1702 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R20	BRIDGESTONE	9 mm
L/H Front Tyre	245/40 R20	BRIDGESTONE	9 mm
R/H Rear Tyre	275/35 R20	BRIDGESTONE	9 mm
L/H Rear Tyre	275/35 R20	BRIDGESTONE	9 mm
4. Description of Damages			
5. General Information			
Accident Date		Inspection Date	
Survey held at	STAR AUTO PERFORMANCE PTE LTD 176 SIN MING DRIVE, #04-05, SIN MING AUTOCARE, SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			