

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0482/2021/KS
DATE : 14-Jun-21
WIP : 31006

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

7 days - ok - Jy - 8 Sep 21

OWNER'S NAME : MR SEETOH KOK NGIN
ADDRESS : 11 JALAN TUMPU
SINGAPORE 678421
TELEPHONE : HP +65 96701381
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800097725-01
VEHICLE NO : **SKN 8191 A**
MODEL CODE : AUDI A6 1.8 TFSI
MODEL YEAR : 15/08/2018
ENGINE NO : CYG 024301
CHASSIS NO : WAUZZZ4G8JN054124
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jun-21
PLACE OF ACCIDENT : CHOA CHU KANG AVE 1, (NEAR KEAT HONG CRESCENT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKN 8191 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$	280.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$	600.00		
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS.	S/N \$	400.00		
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	200.00		
5	TO DISLODGE & REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE & RELAY TRAYS, ELECTRICAL & AUDIO EQUIPMENT. INSPECT FOR DAMAGE & RENEW WHERE NECESSARY.	S/N \$	1,400.00		
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00		
SUB TOTAL LABOUR CHARGES		:	\$ 4,280.00	\$	280.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKN 8191 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 280.00
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	S/N \$ 400.00	\$ 280.00
8	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR AND LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00	\$ 1,750.00
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL TRIM, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANNELLING.	\$ 7,000.00	\$ 2,200.00
10	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT .	S/N \$ 280.00	\$ 280.00
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 19,352.00	\$ 4,982.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 8191 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,268.00	
2	REAR BUMPER FIXING PARTS	1	\$ 273.00	
3	REAR BUMPER GUIDE SECTION LH / RH	2	\$ 66.00	
4	REAR BUMPER GUIDE SECTIONR LH	1	\$ 53.00	
5	REAR FENDER	1	\$ 4,532.00	
6	REAR WINDSCREEN	1	\$ 1,174.00	
7	REAR QUARTER GLASS	1	\$ 390.00	
8	DOOR ENTRANCE STRIP	1	\$ 120.00	
9	REAR WHEEL HOUSING LINER LH	1	\$ 275.00	
10	REAR WHEEL HOUSING LINER ATTACHMENT PARTS LH	1	\$ 73.00	
11	SIDE PANEL TRIM LH	1	\$ 858.00	\$ 686.40
12	SIDE PANEL END CAP LH	1	\$ 88.00	
13	STONE GUARD FILM LH FRONT	1	\$ 118.00	
14	SIDE PANEL TRIM ATTACHMENT CLIP LH	1	\$ 89.00	\$ 71.12
15	SIDE PANEL TRIM ATTACHMENT TAPE LH	1	\$ 16.00	\$ 12.48
16	REAR DOOR LH	1	\$ 4,227.00	\$ 3,381.60
17	REAR DOOR ATTACHMENT PARTS LH	1	\$ 84.00	
18	REAR DOOR OUTER SEAL LH	1	\$ 231.00	\$ 184.40
19	BONDING AGENT	1	\$ 49.00	
20	CLEANING SOLUTION	1	\$ 68.00	
TOTAL SPARE PARTS		:	\$ 16,052.00	\$ 4,336.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 8191 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 4,336.00
21	APPLICATOR	1	\$ 8.00	
22	REAR DOOR CATCH LH	1	\$ 120.00	
23	REAR DOOR SEAL LH - OUTER	1	\$ 283.00	
24	REAR ALUMINIUM RIM LH	1	\$ 1,297.00	\$ 1,037.60
25	1/ GLASS SEALANT	1	\$ 100.00	
26	ACRYLIC SEALANT	S/N	\$ 180.00	
27	CAVITY WAX	S/N	\$ 140.00	
28	STONE CHIP	S/N	\$ 180.00	
29	METAL FILLER POWDER	S/N	\$ 280.00	
30	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
31	SUNDRIES		\$ 350.00	\$ 105.60
TOTAL SPARE PARTS			: \$ 19,190.00	\$ 5,479.20
TOTAL LABOUR CHARGES			: \$ 19,352.00	\$ 4,982.00
GRAND TOTAL			: \$ 38,542.00	\$ 10,461.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-06/08/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT