



NINETEEN
AUTOWERKS

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

not Anthony
16/6/21
L/S + 6000
Zephie After rep-
* like Cecilia 6 days.

Date : 16-Jun-21

Registration no. : GBK3403U / Toyota Hiace Van Turbo 5Dr MT

DOA : 15-Jun-21

Estimate No. : 19A067_GBK3403U_HIACE

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Front door lh	2751.80	X
2	1	Front door weatherstrip lh	226.40	X
3	1	Front door centre pillar outer lh	891.20	✓
4	1	Front door centre pillar mud flap LH	122.50	✓
5	1	Diesel flap	112.00	X
6	1	Diesel filler hose	274.00	X
7	1	Sliding door lh	1716.10	✓
8	1	Sliding door lock switch LH	132.70	✓
9	1	Sliding door inner lock front lh	305.10	✓
10	1	Sliding door inner lock rear lh	305.10	✓
11	1	Sliding door lock actuator lh	286.20	✓
12	1	Sliding door inner board lh	215.40	✓
13	1	Sliding door centre roller assy lh	213.00	X
14	1	Sliding door centre roller railing lh	282.40	X
15	1	Sliding door lower roller assy lh	261.00	✓
16	1	Sliding door lower roller railing lh	293.80	X
17	1	Sliding door lock contact mechanism lh	284.10	✓
18	1	Sliding door weatherstrip lh	282.60	✓
19	1	Sliding door step panel lh	312.00	✓
20	1	Rocker panel lh	879.00	✓
21	1	Rear body panel lh	2219.00	X
			14822.80	

Less 25%

50%

3705.70

11117.10

P-5992
50%
P-2996
S.N- 280
L-2740
6016



NINETEEN
AUTOWERKS

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

Date : 16-Jun-21

Registration no. : GBK3403U / Toyota Hiace Van Turbo 5Dr MT

DOA : 15-Jun-21

Estimate No. : 19A067_GBK3403U_HIACE

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1	Sundries	11 60.00 X
2	1	Front door trimboard clips lh	11 60.00 x
3	1	Front door sealant lh	11 100.00 x
4	1	Front door co. sticker lh	11 80.00 30
5	1	Sliding door inner board clips lh	11 60.00 50
6	1	Front hub cap LH	11 100.00 ✓
7	1	Rear hub cap LH	11 100.00 ✓
			560.00
Parts Total			11677.10

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on rear accident area.	1800.00 1500
2	1	Check wiring system after disconnect and connect.	80.00 20
3	1	R&R upholstery.	11 200.00 X
4	1	R&R LH front door component.	11 100.00 X
5	1	R&R LH sliding door component.	150.00 60
6	1	To conduct wheel alignment.	120.00 60
7	1	To apply undercoating for rust roofing.	200.00 100
8	1	Spray painting on rear accident area.	1800.00 1000
Labour Total			4450.00

Total Parts and Labour Cost of Repair

16127.10

P-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5792
252
P-4454
S.N-280
L-2740
7514
2021
6011.20