

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305473598
 REGN NO : SHC1563A
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 11.03.2020
 DATE/TIME IN : 14.06.2021 13:10
 ACCIDENT DATE : 14.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 FNPS	NUMBER PLATE FRONT W/CASI	1 N	50.00	10.00	45.00	Cnr
0002 04-01-0104-0578-G	COVER-FR BUMPER#	1	430.90	20.00	344.72	Rp
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	Xu7
0004 04-01-0104-2971-G	BRACKET-FR BUMPER SIDE SU	1	35.00	20.00	28.00	45
SUB-TOTAL :						435.32

JOB NATURE

0000 PB	PANEL BEATING	400.00	350	600
0001 SP	SPRAYPAINT CHARGE	300.00	250	
SUB-TOTAL :		700.00		

TOTAL : 1,135.32

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Tanphir 92425747
 'WP' 15/6/21 @ 4pm
 P/P Resurvey of Tanphir
 2 days
 Tanphir @ (Khanh) m.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer