



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1854K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	CRACKED	394.80	394.80
2	REAR BUMPER STAY LH/RH @\$138.10	BENT	276.20	276.20
1	REAR BUMPER LOWER CENTRE MOULDING	CRACKED	155.00	155.00
1	REAR BUMPER UNDER CENTRE COVER	NOT NECESSARY	225.00	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	BOOTLID COVER	BENT	2,480.40	2,480.40
1	BOOTLID LOCK UPPER	NOT NECESSARY	224.00	-
1	BOOTLID H EMBLEM	NOT NECESSARY	38.00	-
1	BOOTLID EMBLEM IONIQ	NECESSARY	31.80	31.30
1	BOOTLID EMBLEM HYBRID	NECESSARY	24.30	24.30
1	BUMPER FOG LAMP	CRACKED	201.00	201.00
2	BUMPER NUMBER LAMP LH/RH @\$85.30	NOT NECESSARY	170.60	-
1	BUMPER HOOK COVER	NOT NECESSARY	94.60	-
1	BOOTLID LAMP LH	NOT NECESSARY	870.40	-
1	TAILLAMP LH	NOT NECESSARY	794.40	-
2	REAR FLECTOR LH/RH	NOT NECESSARY	63.53	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
1	REAR END PANEL	NOT NECESSARY	532.00	-
1	REAR PANEL GARNISH	NOT NECESSARY	346.80	-
1	REAR ANTENNA-SMART KEY	CRACKED	40.50	40.50
2	REAR BUMPER BRACKET LH/RH @\$55.80	NOT NECESSARY	111.60	-
	LESS 20% DISCOUNT		-1,621.28	-907.23
			6,485.10	3,628.92
<u>NETT ITEMS</u>				
1	BOOTLID COMFORT APP STICKER (N)	NECESSARY	40.00	40.00
2	BOOTLID COMFORT/TEL NUMBER STICKER @\$30.00 (N)	NECESSARY	60.00	60.00
1	REAR NUMBER PLATE W/HOLDER (N)	CRACKED	55.00	55.00

Report Ref No. NS/INC21006735/T1tcn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-33.50	-33.50
			301.50	301.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,100.00	525.00
	SPRAY PAINTING CHARGE.		800.00	500.00
	TOWING FEE.		60.00	-
	TUFF KOTE.		120.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			2,140.00	1,085.00
GRAND TOTAL			8,976.60	5,065.42
RECOMMENDED COST OF REPAIRS (CONFIRMED)				5,065.42

Report Ref No. NS/INC21006735/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.