

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21006748/EGS3Q2

Date:

18/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0005549_01

Claimant Vehicle No : SMM9984D**Insured Vehicle No :**

GBG9595E

Date of Loss: 09/06/2021

Nature of Claim:

TP

Claim No:

MFL2021D0002576

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMM9984D**

Make & Model: KIA STONIC, 998cc (A)

Reg. Date: 23/07/2019 (Man. Year: 2019)

Colour: Yellow

Engine Capacity: 998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No:

G3LCKP068144

Chassis No:

KNAD6811VL6319543

Odometer:

19169 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17

Rear Tyre Size:

205/55 R17

Front Left Side: Continental 5 mm

Rear Left Side:

Continental 5 mm

Front Right Side: Continental 5 mm

Rear Right Side:

Continental 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,692.00	1,026.00	666.00	39.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	1,670.00	2,110.00	55.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,472.00	2,696.00	2,776.00	50.73
+ GST 7.00/7.00% (S\$)	383.04	188.72	194.32	50.73

Nett Amount (S\$)	5,855.04	2,884.72	2,970.32	50.73
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,534.17		

INSPECTION

Date of Assignment: 16/06/2021

Date Inspected: 16/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Aug 2021)	
Parts:	N/A	KIA STONIC 998cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM9984D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*PANEL ASSY -FRONT DOOR ,RH	Dented	858.00 FS	*858.00 FS
4	1		*PAD -DOOR O/S HANDLE REAR ,RH	Repair	1.00 FS	*- FS
5	1		*HANDLE ASSY -DOOR OUTSIDE ,RH	Not Necessary	124.00 FS	*- FS
6	1		*COVER -FR DR O/S HDL RH	Not Necessary	17.00 FS	*- FS
7	1		*PAD -DOOR OUTSIDE HANDLE ,RH	Not Necessary	1.00 FS	*- FS
8	1		*BASE ASSY-FR DR O/S HANDLE RH	Not Necessary	27.00 FS	*- FS
9	1		*LATCH ASSY -FFRONT DOOR ,LH	Not Necessary	178.00 FS	*- FS
10	1		*BLACK TAPE-FR DR FRAME UPR ,RH	Necessary	13.00 FS	*13.00 FS
11	1		*TAPE -FR DR BLACK FRAME,RR RH	Necessary	13.00 FS	*13.00 FS
12	1		*MOULDING ASSY -SIDE ,SILL ,RH	Not Necessary	248.00 FS	*- FS
13	1		*GARNISH ASSY -FR DR SIDE RH	Cut	82.00 FS	*82.00 FS
					Total Parts (\$\$)	1,692.00
						1,026.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW RHF DOOR	New	1,920.00	640.00
2	RESPRAY RHF DOOR & RH CENTRE PILLAR	New	1,100.00	550.00
3	REMOVE & REFIT RHF DOOR COMPONENTS	New	320.00	120.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	80.00	80.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	280.00
6	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	0.00
Gross Labour Cost (S\$)			3,780.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >