



CYCLE & CARRIAGE

CY & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
WOO KOK LEUNG, ANDY (HU GUOLIANG)	Cust No/Name LCV10633/WOO KOK LEUNG, ANDY (HU GUOLIAN)
BLK 463 ANG MO KIO AVENUE 10	Reg No/Reg Date SMM9984D*KC17/ 23/07/201
#07-1104	Date In/Mileage / 0
SINGAPORE 560463	Chassis No KNAD6811VL6319543
Contact No Mobile: 98567497	Engine No G3LCKP068144
	Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	16/06/2021/ 11:00	TLE	261 / Edwin Caina	34536			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1920.00
TO RENEW RH F DOOR								
REPAIR RH CENTRE PILLAR								
E PNT98000								1100.00
RESPRAY RH F DOOR & RH CENTRE PILLAR								
E PNT88000								320.00
REMOVE & REFIT RH F DOOR COMPONENTS								80.00
A 54900099								280.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN-PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								80.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								80.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								50.00
Sundries								
M PANEL ASSY-FRONT DOOR,RH					1.00	858.00	00.00	858.00
M PAD-DOOR O/S HANDLE REAR,RH					1.00	1.00	00.00	1.00
M HANDLE ASSY-DOOR OUTSIDE,RH					1.00	124.00	00.00	124.00
M COVER-FR DR O/S HDL RH					1.00	17.00	00.00	17.00
M PAD-DOOR OUTSIDE HANDLE,RH					1.00	1.00	00.00	1.00
M BASE ASSY-FR DR O/S HANDLE RH					1.00	27.00	00.00	27.00
M LATCH ASSY-FRONT DOOR,LH					1.00	178.00	00.00	178.00
M BLACK TAPE-FR DR FRAME UP,RH					1.00	13.00	00.00	13.00
M TAPE-FR DR BLACK FRAME RR,RH					1.00	13.00	00.00	13.00
M MOULDING ASSY-SIDE SILL,RH					1.00	248.00	00.00	248.00
M GARNISH ASSY-FR DR SIDE RH					1.00	82.00	00.00	82.00

SURVEYOR NAME: Steve (LKK) 16/7/21, 2.00pm

SURVEYOR SIGNATURE: [Signature]

Confirm & accepted by

DATE: P/P, M Bel sy

REMARKS: 3 days

7% GST on

Nett

5472.00

5,472.00

383.04

Total Payable

5,855.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts purchased must be confirmed

Authorized signatory and company stamp

Third party survey is on a without prejudice basis.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

No liability for consequential damage. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include supply of additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.