

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD			Ref: CS/SMR21006753/Kuf3	
60 WOODLANDS INDUSTRIAL PARK			Date: 16/06/2021	
E4SINGAPORE 757705			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 1415R		Veh. Inspected	SMA 2904U
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From	HUA YEN		Assign Date	16/06/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/06/2021		Inspection Date	17/06/2021
Survey held at	MUNICH AUTOCARE PTE LTD 60 JALAN LAM HUAT #07-43 CARROS CENTER SINGAPORE 737869			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				