



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR21006754/Guf3n2 Date: 28/07/2021 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 1013B	Veh. Inspected	GBD 1452C
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/06/21/2024	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	16/06/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JN1SC2F24Z0855923	Colour	SILVER
Odometer	91187 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	MICHELIN	5 mm
L/H Front Tyre	195 R15	MICHELIN	5 mm
R/H Rear Tyre	155 R13	MICHELIN	5 mm
L/H Rear Tyre	155 R13	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/06/2021	Inspection Date	16/06/2021
Survey held at	YONG SING MOTOR WORKS 10 DEFU LANE 8 DEFU INDUSTRIAL ESTATE SINGAPORE 539315		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	