ZOOM AUTOWERKS PTE LTD



130 Bedok Reservoir Road, Eunos Spring #08-1339 Singapore 470130 Tel: 9450 7920 ⊠zoomautowerks@gmail.com

Car Number: GBF5938G Model: Nissan Cabstar

Damaged Area: (Rear Right Portion) Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair:

Parts / Material: Special Net Items

Rear Side Fridge Panel RH (W/Insulator)	\$ 3,280.00 Rx
Rear Side Fridge Door RH (W/Insulator)	\$ 2,450.00
Rear Side Fridge Door Lower Hinge RH (Aluminium)	\$ 245.00
Rear side Fridge Door Weather Strip RH	\$ 495.00 Cut /
Rear Side Fridge Door Frame RH (Aluminium Cladding - Horizontal)	\$ 680.00 H/
Rear Side Fridge Door Frame RH - (Aluminium Cladding - Vertical)	\$ 720.00 bt /
Rear Taillamp RH	\$ 295.86 Cra/
Rear Taillamp Bracket RH	\$ 95.60 ht/
Rear Reinforcement Damper Rubber	\$ 175.00 Urt

Total S/N Parts: \$ 8,436.46 220586

Labour:

To Remove, Repair & Renew Rear Affected Accident Areas

To Putty, Spray Paint on Affected Accident Areas

To Check & Re-Connect all electrical wiring

To Conduct Water Leakage Test

To Rust Proof Affected Areas

Total Labour: \$ 2,700.00 \$00

 TOTAL SPECIAL NET ITEM:
 \$ 8,436.46

 TOTAL LABOUR:
 \$ 2,700.00

 TOTAL REPAIR COST:
 \$ 11,136.46

4095.86 415\$3250 ·61435*

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM:

RECOMMENDED NUMBER OF DAYS:

SURVEY BY / SURVEYOR FIRM:

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufuh 97495749
16/6/210415pm
LISRESULUS anterragair
Gdays
+ aufuh@lkkduto.com