

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/SMG2778G/TPC

AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way
#07-16
Singapore 079120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

QUOTATION

Dear Sir,

Cost of Repair to Vehicle SMG2778G

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$S)	AMOUNT (\$S)
1.	RR LICENSE LAMP @ \$17.00 X nn	2	34.00	34.00
2.	LH REFLECTOR RR BUMPER 1 X nn	1	61.90	61.90
3.	RH REFLECTOR RR BUMPER X nn	1	61.90	61.90
4.	ORNAMENT - BACK DOOE QASHAI / AK	1	94.40	78 ✓ 94.40
5.	EMBLEM- REAR NISSAN X nn	1	64.90	64.90
6.	PLATE - LUGGAGE REAR GARNISH X nn	1	68.80	68.80
7.	HATCHBACK DOOR STAY @ \$227.30 X nn	2	454.60	454.60
8.	WEATHER STRIPE HATCHBACK DOOR 1 ✓ TN	1	167.00	167.00 ✓
9.	HATCHBACK DOOR CENTRE FINISHER	1	X nn 352.00	352.00
10.	RUBBER - DUM X nn	1	63.80	63.80
11.	GLASS - HATCHBACK DOOR X nn	1	973.20	973.20
12.	HATCHBACK DOOR / 00	1	2980 ✓ 3,062.60	3,062.60
13.	HATCHBACK DOOR LOCK / 0T	1	190.50	145 ✓ 190.50


14.	STRIKER- HATCHBACK DOOR	X nn	1	34.80	34.80	
15.	LH STAY RR BUMPER	? / RT	1	141.00	141.00	✓
16.	RH STAY RR BUMPER	X / BT	1	141.00	141.00	✓
17.	REINFORCEMENT RR BUMPER	? / BT	1	691.50	691.50	✓
18.	ENERGY ABSORBER RR BUMPER	? X nn	1	141.40	141.40	
19.	LH SIDE BRACKET RR BUMPER	/ BR	1	38.90	38.90	✓
20.	RH SIDE BRACKET RR BUMPER	X nn	1	38.90	38.90	
21.	TOW HOOK COVER	X nn	1	18.80	18.80	
22.	REAR BUMPER	/ 00	1	796.70	796.70	✓
23.	SENSOR - REVERSE	/ CAT	1	200 / 250.00	nettt 250.00	
24.	TAIL LAMP SN	X nn	1	346.90	346.90	
25.	TAILGATE LAMP SN	X nn	1	231.30	231.30	
26.	REAR W/SCREEN SEALANT	/ nrc	1	40 / 80.00	nettt 80.00	
27.	SUNDRIES	/ nrc	1	50.00	30 / 50.00	nettt
28.	LABOR CHARGES TO REPAIR RR END PANEL AND BOTH RR FENDER, RENEW HATCHBACK DOOR & REAR BUMPER		1	500 / 1,680.00	400 / 1,680.00	
29.	CHARGES TO SPRAY PAINTING SAME		1	500 / 1,250.00	400 / 1,250.00	
30.	APPLY SEALANT TO HATCHBACK DOOR		1	100.00	30 / 100.00	
31.	RENEW REAR WINDSCREEN GLASS		1	180.00	120 / 180.00	
32.	RENEW RR WINSCEEN GLASS SALR FILM		1	150.00	100 / 150.00	
33.	REMOVE AND INSTALL HATCHBACK DOOR MECHANISM		1	80.00	50 / 80.00	
34.	REMOVE AND INSTALL REVERSE CAMERA		1	120.00	30 / 120.00	
35.	REMOVE AND INSTALL BOTH RR COMB LAMP TO FACILITAE REAR RUMPER REPLACEMENT		1	48.00	20 / 48.00	
36.	RENEW REVERSE SENSOR		1	110.00	20 / 110.00	
37.	SUPPLY REAR LICENSE PLATE		1	40.00	X / 40.00	

			SUB-TOTAL	SS12,408.80

- Price before 7% gst

Thank you.

Yours faithfully,



Winnie Chai

HP: 9850-9666

Steve (CLKK) WML ML

17/6/21, 10.00am

L/S

My PL sy

5 dys

P-5179.10

-10%

4661.19

n-270

L-1370

6301.19

L/S-5040.95

=5050

5050