## COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE

DATE: 16/06/21

3P INSURANCE: AIG ASIA  $\varphi(\rho)$ 

MODEL: HYUNDAI IONIQ

SURVEYOR: NA

VEH NO .: SHA2202X

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS	56 5
	Rear Bumper	1		/\$459.40 a	te -
į.	Rear Bumper Centre Moulding	1	1	/\$451.25 0	int
ļ	Rear Bumper Side Bracket RH	1		\$55.80 %	· uy
l	Rear Bumper Cover Clips	10	\$2.20	1\$22.00 M	and the second s
	Rear Bumper Reflector RH	1		\$41.45 ⋉	144
	Rear Wheel Cap RH	1		× \$346.40 °	6
	Rear Fender Shield RH	1		\$73.60	un.
	SPARE PARTS SUB TOTAL			\$1,449.90	1279.05
1	LESS 20%			\$289.98	1023.24
	DISCOUNTED SPARE PARTS TOTAL			\$1,159.92	ā)
S R	Panel Beating – Rear Fender RH Spray Painting  VI Reverse Sensor Vheel Alignment			\$800.00 \$ \$600.00 \$ \$120.00 \$	,0
	LABOUR TOTAL			\$1,640.00	1135
	ESTIMATE TOTAL		F	\$2,799.92	92158.24 02 den #
is an initial the vehicle	estimate based on a visual inspection of the above vehicle. is surveyed by a motor Surveyor appointed by the insurance	The final	repair quantum v	will be prepared	ر: با ب

Tarfri 9741)749 up A 17/6/21 & 415 pm

pp Nesny before p fastir althurantour

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer