

AFORT TRANSPORTATION PTE LTD

PAIR ESTIMATE

Vehicle No. : SHD4084R

Make : HYUNDAI

Model : IONIQ(G2)

Date: 15/06/2021

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR BUMPER TOWING COVER			\$98.80
1	LICENCE LAMP			\$85.30
1	ANTENNA ASSY - SMARTK			\$40.50
1	BOOTLID			\$2,480.40
1	BOOTLID HYUNDAI PLATE			\$24.30
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
			473.25	
	SUB TOTAL			\$4,468.85
	LESS 20%			\$893.77
	DISCOUNTED TOTAL			\$3,575.08
1	REAR BUMPER RUBBER MAT			\$50.00
1	BOOTLID COMFORT TEL NO STICKER,			\$35.00
1	BOOTLID COMFORT LOGO STICKER			\$30.00
1	REAR NUMBER PLATE + TRIM COVER			\$45.00
1	BOOTLID COMFORT APP STICKER			\$30.00
1	REAR BUMPER REVERSE SENSOR			\$180.00
				\$320.00
	Labour Charge			
	PANEL BEATING			\$800.00
	SPRAY PAINTING CHARGE			\$600.00
	WIRING CHARGE			\$50.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
				\$1,530.00
	TOTAL LABOUR			
	ESTIMATE TOTAL		91233.60	\$5,425.08
			2 days	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: 6/30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
WR 15/6/21 2:40pm
p/p Resurvey after repair, new parts.
2 days
Tanpin @ Kuantan