



Re: E?2651?2021 - SBS3747K with GAS BUS SG1057T -

Yao Tianhao <yaoth@sbstransit.com.sg>

Wed 6/16/2021 12:17 PM

**Estimate for**

| Stock Code | Description                            | Quantity | Total Material cost(\$\$) |
|------------|--|----------|---------------------------|
| 30541715   | REAR REVERSE LAMP;B9TL EU5             | 1        | \$81.00                   |
| 30541727   | LED STOP/TAIL LIGHT 24V;30541713 1 LED | 1        | \$66.00                   |
| 30541726   | LED INDICATOR LIGHT 24V;30541714 1 LED | 1        | \$67.00                   |
| 30311711   | NUMBER PLATE RECESS PAN;EXT.RR         | 1        | \$166.00                  |
| 30750462   | DOOR.LOWER BOOT                        | 1        | \$1,140.00                |
| 42311220   | EMBLEM;DECALS                          | 1        | \$48.00                   |
| 30750006   | DOOR RETAINER;EXTERIOR DOOR            | 2        | \$15.00                   |
| 30750754   | CHECK STRAP.BOOT DOOR.RR               | 1        | \$23.00                   |
| 30750071   | REAR A/C ACCESS DOOR ASSY;RR ENG DR    | 1        | \$3,176.00                |
| 42311205   | PLATE;2MX1M;SOUND ABSORBER             | 1        | \$466.00                  |

cwa ✓  
 cwa ✓  
 cwa ✓  
 cwa ✓  
 bt ✓  
 rec ✓  
 bt ✓  
 bt ✓  
 bt ✓  
 rec ✓

- Parts cost: \$ 5248 ✓
- Contractor Labour cost: \$ 1050 +gst ✓
- Workshop Labour cost: \$ not req by lkk
- Advertisement Cost: \$ 0
- Repair period: 3 days ✓

Tanpin 27495749  
 'WP' 17/6/21 @ 340pm  
 Resurvey new parts.  
 @ 3 days  
 COR not finalise with workshop.

- Tow Cost: \$ 0
- Loss of use: \$ not req by lkk
- Overheads: \$ 1250.40 X N N

**LKK Auto Consultants** hence notify the Repairer of the following:
 

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer  
 Signature:  
 Date: