

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT RH DOOR	1,725.00 ✓	-10.00	1,552.50 <i>bt -</i>
2	1	FRONT RH DOOR OUTER HANDLE	142.50 ✓	-10.00	128.25 <i>dis ✓</i>
3	1	FRONT RH DOOR GLASS OUTER MOULDING	165.00	-10.00	148.50 <i>X un</i>
4	1	FRONT RH DOOR GLASS REGULATOR	330.00	-10.00	297.00 <i>X un</i>
5	1	FRONT RH SIDE MIRROR	642.00 ✓	-10.00	577.80 <i>ent -</i>
6	1	FRONT RH DOOR HINGE TOP	90.00	-10.00	81.00 <i>X un</i>
7	1	FRONT RH DOOR HINGE BOTTOM	69.00	-10.00	62.10 <i>X un</i>
8	1	FRONT RH DOOR INNER BOARD	0.00	-10.00	0.00 <i>X un</i>
9	1	FRONT RH DOOR TOP CHROME	105.00	-10.00	94.50 <i>X un</i>
10	1	REAR RH DOOR	1,725.00 ✓	-10.00	1,552.50 <i>bt -</i>
11	1	REAR RH DOOR HINGE TOP	90.00	-10.00	81.00 <i>X un</i>
12	1	REAR RH DOOR HINGE BOTTOM	90.00	-10.00	81.00 <i>X un</i>
13	1	REAR RH DOOR GLASS OUTER MOULDING	165.00	-10.00	148.50 <i>X un</i>
14	1	REAR RH DOOR TOP CHROME	105.00	-10.00	94.50 <i>X un</i>
15	1	REAR RH DOOR GLASS REGULATOR	480.00	-10.00	432.00 <i>X un</i>
16	1	REAR RH DOOR INNER BOARD	0.00	-10.00	0.00 <i>X un</i>
17	2	REAR RH DOOR GLASS	660.00	-10.00	594.00 <i>X un</i>
18	1	REAR RH DOOR GLASS REGULATOR	480.00	-10.00	432.00 <i>X un</i>
19	1	REAR RH DOOR GLASS REGULATOR MOTOR	210.00	-10.00	189.00 <i>X un</i>
20	1	RH SIDE SKIRT	345.00	-10.00	310.50 <i>Ry</i>
21	1	FRONT RH FENDER	570.00	-10.00	513.00 <i>Ry</i>
22	1	FRONT RH FENDER EMBLEM	75.00 ✓	-10.00	67.50 <i>nt</i>
23	1	REAR RH FENDER	2,250.00	-10.00	2,025.00 <i>Ry</i>
24	1	REAR BUMPER	1,125.00	-10.00	1,012.50 <i>Ry</i>
25	1	REAR BUMPER RH SIDE RETAINER	78.00	-10.00	70.20 <i>X un</i>
26	1	REAR BUMPER RH REFLECTOR	48.00	-10.00	43.20 <i>X un</i>
27	1	REAR RH TAILLAMP	390.00	-10.00	351.00 <i>X un</i>
28	1	FRONT RH DOOR RUBBER	202.50 ✓	-10.00	182.25 <i>?nt</i>
29	1	REAR RH DOOR RUBBER	202.50 ✓	-10.00	182.25 <i>?nt</i>

Total Parts (\$\$) 11,303.55

4243.05

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT RH DOOR STICKER	60.00	0.00	60.00 <i>nt</i>
2	1	REAR RH DOOR STICKER	60.00	0.00	60.00 <i>nt</i>
3	1	FRONT RH WHEEL RIM	350.00	0.00	350.00 <i>ent</i>
4	1	REAR RH WHEEL RIM	350.00	0.00	350.00 <i>ent</i>
5	1	FRONT RH TYRE	250.00	0.00	250.00 <i>X un</i>
6	1	REAR RH TYRE	250.00	0.00	250.00 <i>X un</i>
7	1	REAR BUMPER SENSOR	300.00	0.00	300.00

Sub Total (\$\$) 1,620.00

820

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Reset Power Window.	120.00	0.00	120.00 <i>80</i>
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>30</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
3	1	To Computer Reset and Re-program all fault code.	350.00	0.00	350.00 ²⁰⁰
4	1	To Transfer Door.	80.00	0.00	80.00 ✓
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	250.00	0.00	250.00 ✗
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	950.00	0.00	950.00 ⁸⁰⁰

Gross Labour Cost (\$\$) 1,830.00 ¹¹⁹⁰

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	80.00	0.00	80.00 ³⁰
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00 ✗ ⁴⁰
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,000.00	0.00	1,000.00 ✓ ¹⁰³⁰

Gross Labour Cost (\$\$) 1,125.00

< END OF ESTIMATES >

Tanpin 97475749/67563561
 WP 18/6/21 @ 2pm
 L/S Rosny after repair
 6 days
 Tanpin @ lkhauto.com

4243.05
 820
 1190
 1030
 7283.05
 L/S 5800
 6 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: