

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0486/2021/GW
DATE	:	15-Jun-21
WIP	:	

Denise.

\$10021.30.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY

CHINA TAIPING INSURANCE (SG) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME	:	MR. TSE YAU SHING, WILLY
ADDRESS	:	1E SHELFORD ROAD #05-30 SINGAPORE 286890
TELEPHONE	:	HP +65 91156288
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	5109056612-01
VEHICLE NO	:	SKS 8602 E
MODEL CODE	:	A4 1.8 TFSI MU
MODEL YEAR	:	13/5/2015
ENGINE NO	:	CJE098872
CHASSIS NO	:	WAUZZZ8KXFA104776
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	7-Jun-21
PLACE OF ACCIDENT	:	BLK 1E SHELFORD ROAD (BASEMENT CARPARK)



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKS 8602E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY.	S/N \$ 360.00 X	360
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 ✓	350
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00 X	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO REPAIR BOTH FRONT FENDER TOP SUPPORTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED.	\$ 4,900.00 ✓	1400 1400
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, HINGES AND BONNET. ✓	X \$ 3,000.00 ✓	2100 2100
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	192
TOTAL LABOUR CHARGES		: \$ 10,002.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 8602 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Rehind</i>	1	\$ 2,560.00	✓ ✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 259.00	x
3	FRONT BUMER CLOSING ELEMENT-LOWER CENTRE <i>cracked</i>	1	\$ 228.00	+ 227.50
4	FRONT BUMPER GRILLE-LOWER CENTRE <i>cracked</i>	1	\$ 135.00	✓
5	FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE <i>new</i>	1	\$ 194.00	+
6	FRONT BUMPER SUPPORT ELEMENT-UPPER <i>new</i>	1	\$ 59.00	x
7	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,090.00	✓
8	FRONT AIR GUIDE GRILLE-LH <i>cracked</i>	1	\$ 135.00	x
9	FRONT WHEEL SPOILER-LH <i>new</i>	1	\$ 51.00	x
10	FRONT BUMPER REINFORCEMENT BEAM <i>the new</i>	1	\$ 926.00	x
11	FRONT FOAM FILLER PIECE <i>cracked</i>	1	\$ 124.00	?
12	FRONT BUMPER REINFORCEMENT BEAM SUPPORT-LH/RH <i>new</i>	1	\$ 26.00	x
13	FRONT BUMPER GUIDE SECTION-LH <i>new</i>	1	\$ 36.00	+
14	FRONT BUMPER COVER <i>cracked</i>	1	\$ 127.00	✓
15	STICKER FOR SIGN 'CAUTION' <i>new</i>	1	\$ 14.00	x 13.60
16	STICKER FOR AIR CONDITIONER <i>new</i>	1	\$ 30.00	✓
17	SIGNAL HORN-LH <i>new</i>	1	\$ 201.00	x
18	SIGNAL HORN SPRING SHACKLE-LH <i>new</i>	1	\$ 25.00	x
19	FRONT FENDER-LH <i>cracked</i>	1	\$ 990.00	✓
20	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 57.00	x
SUB TOTAL SPARE PARTS		:	\$ 7,267.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO, SKS 8602 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER BRACKET-LH <i>Neu</i>	1	\$ 53.00	*	
22	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH <i>Neu</i>	1	\$ 49.00	*	
23	FRONT FENDER BRACE-LH <i>Neu</i>	1	\$ 118.00	*	
24	FRONT WHEEL HOUSING LINER-LH <i>Neu</i>	1	\$ 240.00	*	
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Neu</i>	1	\$ 45.00	*	
26	FRONT STONE CHIP GUARD <i>Neu</i>	1	\$ 73.00	*	
27	ADHESIVE TAPE	1	\$ 55.00	*	
28	BONNET <i>Repar</i>	1	\$ 3,241.00	*	
29	BONNET PROTECTIVE FILM	1	\$ 46.00	+	
30	BONNET LID HINGE-LH/RH	2	\$ 148.00	*	
31	BONNET CATCH HOOK	1	\$ 140.00	+	
32	BONNET EDGE PROTECTION	1	\$ 28.00	+	
33	BONNET LID LOCK WITH MICRO SWITCH <i>Neu</i>	1	\$ 214.00	*	
34	BONNET LOCK COVER <i>Neu</i>	1	\$ 23.00	+	
35	HEADLIGHT MOUNTING-LH <i>cracked</i>	1	\$ 118.00	✓*	
36	HEADLIGHT BRACKET-LH <i>Neu</i>	1	\$ 106.00	+	
37	HEADLIGHT-LH <i>Neu</i>	1	\$ 2,343.00	+	
38	FRONT FOG LAMP-LH <i>Neu</i>	1	\$ 262.00	*	
39	HEADLIGHT LIFT CYLINDER-LH <i>Neu</i>	1	\$ 210.00	*	
40	HOSE FOR HEADLIGHT WASHER SYSTEM <i>Neu</i>	1	\$ 182.00	*	
SUB-TOTAL SPARE PARTS			\$ 7,694.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKS 8602 E

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT LOCK CARRIER <i>new</i>	1	\$ 1,016.00	<i>x</i>
42	FRONT LOCK CARRIER BRACKET-LH <i>new</i>	1	\$ 45.00	<i>x</i>
43	TEMPERATURE SENSOR BRACKET-LH <i>new</i>	1	\$ 19.00	<i>x</i>
44	COOLANT FOR RADIATOR <i>new</i>	6	\$ 142.00	<i>x</i>
45	RADIATOR AIR GUIDE-LH <i>new</i>	1	\$ 27.00	<i>x</i>
46	FRONT NO. PLATE <i>new</i>	S/N	\$ 60.00	<i>✓</i>
47	SUNDRIES <i>Nec.</i>		\$ 300.00	<i>✓</i> 9.2
TOTAL SPARE PARTS		:	\$ 16,570.00	
TOTAL LABOUR CHARGES		:	\$ 10,002.00	
GRAND TOTAL		:	\$ 26,572.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian Lj
22/06/21

Not Authorised, 06 Days. H.S.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT