

REC. P



AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD
 ROC: 202022890H
 BLOCK 9008
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

Estimation

Date

Vehicle

SLZ 8869 D

Make/Model

MERCEDES E200

Chassis No.

WDD2130132A235923

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	TAIL LAMP LH	1	\$ 894	-
2	TAIL LAMP LOWER BRACKET LH	1	\$ 370	-
3	REAR BUMPER	1	\$ 1670	-
4	REAR BUMPER REFLECTOR LH	1	\$ 370	-
5	REAR BUMPER REVERSE SENSOR SET	1	255	\$ 255 -
6	REAR BUMPER LOWER	1	\$ 478	-
7	REAR BUMPER LOWER CHROME	1	\$ 388	-
8	REAR BUMPER RETAINER LH	1	\$ 126	-
9	REAR BUMPER CENTER BRACKET	1	\$ 105	-
10	REAR BUMPER CARRIER	1	\$ 969	-
11	REAR BUMPER REINFORCEMENT BAR	1	\$	-
12	REAR BUMPER SPONGE	1	\$	-
13	REAR BUMPER UNDERCOVER	1	\$	-
14	REAR WINDSCREEN MOULDING	1	\$ 254	-
15	REAR FENDER LH	1	\$ 1600	-
16	REAR FENDER COWLING LH	1	\$ 342	-
17	REAR WHEELHOUSE LH	1	\$	-
18	REAR DOOR LH	1	\$ 2337.96	-
19	REAR DOOR WEATHERSTRIP LH	1	\$ 305.97	-
20	REAR ABSORBER LH	1	\$ 565	-
21	REAR UPPER ARM LH	1	\$	-
22	REAR LOWER ARM LH	1	\$ 715.43	Xun
23	REAR CONTROL ARM LH	1	\$	-
24	REAR STRAIGHT ARM LH	1	\$	-
25	REAR KNUCKLE ARM LH	1	\$ 1488.20	Xun
26	REAR KNUCKLE BEARING LH	1	\$	-
27	REAR BEARING HUB LH	1	\$	-
28	REAR RIM LH	1	\$ 1050	mb
			Total	\$ 14,083.56
			Less 10%	\$ 6561
			Total	\$ 5904.90

14,083.56

12,675.20

S/Nett Items				
1	TAIL LAMP CLIPS	10 pcs	50	\$ 50.00
2	REAR BUMPER CLIPS	30 pcs	100	\$ 100.00
3	REAR FENDER SEALANT	60 pcs	200	\$ 200.00

4	REAR FENDER COWLING LH	wp's nec	20	1	100	\$	100.00
5	REAR WHEELHOUSE SEALANT		X N/A	1	150	\$	150.00
6	REAR TYRE LH		X N/A	1	800	\$	800.00
						Total	\$ 1,400.00

120

LABOUR						
1	PANEL BEATING ON AFFECTED AREAS		1400	1	\$ 800	1,400.00
2	SPRAY PAINT ON AFFECTED AREAS		1000	1	\$ 750	1,000.00
3	TO RNR REAR WINDSCREEN		400	1	\$ 120	400.00
4	TO RNR REAR EXHAUST		250	1	\$ X N/A	250.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION		150	1	\$ 30	150.00
6	TO RNR REAR INNER TRIM AND UPHOISTERY		400	1	\$ 60	400.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST		250	1	\$ 80	250.00
8	TO RNR UNDERCARRIAGE		300	1	\$ 150? photo	300.00 X N/A
9	TO CHECK WHEEL BALANCING		250	1	\$ 30	250.00
10	TO CHECK WATER LEAK		150	1	\$ 30	150.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS		1200	1	\$ 280 280	1,200.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION		150	1	\$ 30	150.00
13	TO PERFORM RUST PROOFING		400	1	\$ 30	400.00
14	TO RNR REAR DOOR MECHANISM			1	\$ 40 X N/A	
						2240

Total Labour	\$	6,300.00
Parts Replacement Amount	\$	1,400.00
Total Amount	\$	7,700.00

20,375.20

Tanflem 97495749
 = WP' 18/6/21 @ 4pm
 vs Bony after repair
 tanflem@lkkauto.com
 6 days

5904.90
 120
 2240
 8264.90
 4/s \$6600 #
 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: