

Estimation

Date
Vehicle SLZ 8869 D
Make/Model MERCEDES E200
Chassis No. WDD2130132A235923

| No. | Description | Unit | Unit Price | Amount |
|-----|--------------------------------------|------|--------------|---------------------|
| | Parts Replacment | | | |
| 1 | TAIL LAMP LH | 1 | | \$ 298.70 |
| 2 | TAIL LAMP LOWER BRACKET LH | 1 | | \$ 349.00 |
| 3 | REAR BUMPER | 1 | | \$ 2,011.82 |
| 4 | REAR BUMPER REFLECTOR LH | 1 | 110 | \$ 110 |
| 5 | REAR BUMPER REVERSE SENSOR SET LH x1 | 1 | 302 | \$ 320 |
| 6 | REAR BUMPER LOWER | 1 | 340 | \$ 340 |
| 7 | REAR BUMPER LOWER CHROME | 1 | 210 | \$ 210 |
| 8 | REAR BUMPER RETAINER LH | 1 | | \$ 82.50 |
| 9 | REAR BUMPER CENTER BRACKET | 1 | 188 | \$ 188 |
| 10 | REAR BUMPER CARRIER | 1 | 188 | \$ 188 |
| 11 | REAR BUMPER REINFORCEMENT BAR | 1 | 798 | \$ 798 |
| 12 | REAR BUMPER SPONGE | 1 | 310 | \$ 310 |
| 13 | REAR BUMPER UNDERCOVER | 1 | 210 | \$ 210 |
| 14 | REAR WINDSCREEN MOULDING | 1 | | \$ 320.40 |
| 15 | REAR FENDER LH | 1 | | \$ 2,644.99 |
| 16 | REAR FENDER COWLING LH | 1 | | \$ 195.30 |
| 17 | REAR WHEELHOUSE LH | 1 | 1055 | \$ 1055 |
| 18 | REAR DOOR LH | 1 | 1938 | \$ 1938 |
| 19 | REAR DOOR WEATHERSTRIP LH | 1 | | \$ 391.00 |
| 20 | REAR ABSORBER LH | 1 | 890 | \$ 890 |
| 21 | REAR UPPER ARM LH | 1 | 865 | \$ 865 |
| 22 | REAR LOWER ARM LH | 1 | 1140 | \$ 1140 |
| 23 | REAR CONTROL ARM LH | 1 | 945 | \$ 945 |
| 24 | REAR STRAIGHT ARM LH | 1 | 1420 | \$ 1420 |
| 25 | REAR KNUCKLE ARM LH | 1 | | \$ 1,200 |
| 26 | REAR KNUCKLE BEARING LH | 1 | | \$ 725.00 |
| 27 | REAR BEARING HUB LH | 1 | 1055 | \$ 1055 |
| 28 | REAR RIM LH | 1 | | \$ 1078.00 |
| | | | Total | \$ 21,578.71 |
| | | | Less 10% | \$ 2,157.87 |
| | | | Total | \$ 19,420.84 |

| S/Nett Items | | Unit | Unit Price | Amount |
|--------------|---------------------|------|------------|-----------|
| 1 | TAIL LAMP CLIPS | 1 | 50 | \$ 50.00 |
| 2 | REAR BUMPER CLIPS | 1 | 100 | \$ 100.00 |
| 3 | REAR FENDER SEALANT | 1 | 200 | \$ 200.00 |

| | | | | | | | |
|---|-------------------------|-------|----|---|--------------|----|-----------------|
| 4 | REAR FENDER COWLING LH | de fs | 20 | 1 | 100 | \$ | 100.00 |
| 5 | REAR WHEELHOUSE SEALANT | | X | 1 | 150 | \$ | 150.00 |
| 6 | REAR TYRE LH | | X | 1 | 800 | \$ | 800.00 |
| | | | | | Total | \$ | 1,400.00 |

| LABOUR | | | | | | | |
|--------|---|--|--|---|------|----|-------------------------------|
| 1 | PANEL BEATING ON AFFECTED AREAS | | | 1 | 1400 | \$ | 1400 1000 1,400.00 |
| 2 | SPRAY PAINT ON AFFECTED AREAS | | | 1 | 1000 | \$ | 750 1,000.00 |
| 3 | TO RNR REAR WINDSCREEN | | | 1 | 400 | \$ | 120 400.00 |
| 4 | TO RNR REAR EXHAUST | | | 1 | 250 | \$ | X 250.00 |
| 5 | TO CHECK WIRING AND TAIL LAMP FUNCTION | | | 1 | 150 | \$ | 30 150.00 |
| 6 | TO RNR REAR INNER TRIM AND UPHOISTERY | | | 1 | 400 | \$ | 60 400.00 |
| 7 | TO CHECK WHEEL ALIGNMENT AND ADJUST | | | 1 | 250 | \$ | 80 250.00 |
| 8 | TO RNR UNDERCARRIAGE | | | 1 | 300 | \$ | 150? photo 300.00 |
| 9 | TO CHECK WHEEL BALANCING | | | 1 | 250 | \$ | 30 250.00 |
| 10 | TO CHECK WATER LEAK | | | 1 | 150 | \$ | 30 150.00 |
| 11 | TO PERFORM DIAGNOSTIC AND CLEAR FAULTS | | | 1 | 1200 | \$ | 1200 280 1,200.00 |
| 12 | TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION | | | 1 | 150 | \$ | 20 150.00 |
| 13 | TO PERFORM RUST PROOFING | | | 1 | 400 | \$ | 30 400.00 |
| 14 | TO RNR REAR DOOR MECHANISM | | | 1 | | \$ | X 40 - |

| | | |
|---------------------------------|----|-----------------|
| Total Labour | \$ | 6,300.00 |
| Parts Replacement Amount | \$ | 1,400.00 |
| | | 28,572.31 |
| Total Amount | \$ | 7,700.00 |

Taufik 97495749
 'WP' 18/6/21 @ 4pm
 via Ronny after repair
 Taufik @ 11h outside in
 6 days



AP AUTOMOTIVE SERVICES PTE LTD
 ROC: 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

Estimation

Date
 Vehicle SLZ 8869 D
 Make/Model MERCEDES E200
 Chassis No. WDD2130132A235923

| No. | Description | Unit | Unit Price | Amount |
|-----|-------------------------------|------|--------------|---------------------|
| | Parts Replacment | | | |
| 1 | REAR FENDER AIR VENT LH | 1 | | \$ 195.30 - |
| 2 | REAR PROXIMITY SENSOR LH | 1 | | \$ 768.00 - |
| 3 | EXHAUST HEAT SHIELD TOP | 1 | | \$ 326.00 - |
| 4 | EXHAUST HEAT SHIELD BOTTOM LH | 1 | | \$ 279.00 - |
| | | | Total | \$ 1568.30 - |
| | | | Less 10% | \$ 156.83 - |
| | | | Total | \$ 1411.47 - |