

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 05 Aug 2021

Preliminary Advice

Insured Vehicle No	: GBA9857G	Accident Date	: 14/06/2021
TP Vehicle No	: SMH1786M	Assignment Date	: 17/06/2021
Make	: TOYOTA VIOS	Est. Duration of Repair	: 3
Date of Inspection	: 18/06/2021		
Inspection At	: BW WORKSHOP SERVICES PTE LTD (HQ) 291 KAKI BUKIT AVENUE 1, SHUN LI INDUSTRIAL PARK SINGAPORE 416080		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,485.50
Revised Amount	:S\$	1,847.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,847.25

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.