

BW WORKSHOP SERVICES PTE LTD

291 KAKI BUKIT AVE 1 SHUN LI

INDUSTRIAL PARK

Singapore 416080

6289 8800

workshop_admin@bw.com.sg

GST Registration No. : 201504834E

Company Registration No. 201504834E



LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATES NO. 1282**DATE 16/06/2021**

Xiao Chen

Estimates

ADDRESS

CHINA TAIPING INSURANCE

(SINGAPORE) PTE LTD

CHINA TAIPING INSURANCE

(SINGAPORE) PTE LTD

VIN NUMBER

SMH1786M / MR2B23F3801158062

MAKE & MODEL

TOYOTA VIOS 1.5 E

MILEAGE

-

ACTIVITY	QTY	RATE	AMOUNT
REAR BUMPER @ \$657 <i>rehd</i>	1	492.75	✓ 492.75
REAR BUMPER SIDE RETAINER (RH) @ \$147 <i>rehd</i>	1	110.25	✓ 110.25
REAR TAIL LAMP (RH) @ \$579 <i>rehd</i>	1	434.25	✓ 434.25
REAR TAIL LAMP BRACKET (RH) @ \$109 <i>rehd</i>	1	81.75	✓ 81.75
REAR FENDER (RH) @ \$1182 <i>rehd</i>	1	886.50	✓ 886.50
Subtotal: 2,005.50			
REAR BUMPER CLIPS -S/N <i>rehd</i>	10	8.00	30 80.00
Subtotal: 80.00			
TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	4	200.00	300 800.00
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	2	200.00	✓ 400.00
TO REMOVE AND REFIT REVERSE SENSOR	1	100.00	50 100.00
TO FOCUS TAILLAMPS . TO CHECK WIRING AND LIGHTING OPERATION	1	100.00	30 100.00
Subtotal: 1,400.00			

Please feel free to contact us again if you have any queries on our quotation.

SUBTOTAL
GST TOTAL
TOTAL

3,485.50
0.00

SGD 3,485.50

We look forward to hearing from you soon.

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

Adrian Lj
P/P 18/06/21

03Days

1847-25
CP/P)