

TP ALG-
Justin.

KMHADU41BR9U647680

Page No. 1

VEHICLE NO SJM 3061S HYUNDAI AVANTE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYORS ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front Bumper <i>Repld</i> <i>RH 2nd</i>		1125.00	✓ 442
2	Front Bumper Side Retainer L/R @ \$52.50		105.00	35
1	RHS Headlamp <i>RH 1st</i>		982.00	x.
1	RHS Side view mirror assy complete <i>auled</i>		652.00	✓
1	RHS Front Shock Absorber <i>Bert</i>		492.00	✓ 349.
1	RHS Front Lower Arm <i>Bert</i>		288.00	✓
1	RHS Front Knuckle Arm <i>2nd</i>		392.00	✓
1	RHS Front Wheel Bearing <i>2nd</i>		198.00	✓
1	RHS Front stabiliser bar <i>2nd</i>		142.00	x.
1	RHS Front door <i>2nd</i>		0.00	x.
1	RHS Front fender <i>Dischld</i>		752.00	✓ 437
1	RHS Front fender inner splash shield <i>tom</i>		254.00	175
		REPAIR		
		less 20%	5382.00	
			1076.40	20%
			4305.60	
	SPECIAL NETT ITEMS			
1	RHS Front sports rim <i>auled</i>		980.00	450
2set	Bumper clips <i>run</i>		60.00	30
1set	RHS Front fender inner shield clips <i>run</i>		60.00	30
	<i>Type RH</i> <i>Perched</i>			
	TOTAL PARTS		5405.60	560

180(SW)
✓

VEHICLE NO SJM 3061S HYUNDAI AVANTE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas; replace the damaged parts and components.	1200.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	750.00	700
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions and focus headlamp beam	250.00	30
4	To provide anti-rust treatment on affected areas	120.00	40
5	To carry out computerised wheel alignment test	120.00	80
6	To remove and replace RHS front undercarriage parts (suspension system)	250.00	220
	Labour Total :	2690.00	1700
	TOTAL (PARTS & LABOUR):	8095.60	

NOTE: The parts listed in this PRELIMINARY ESTIMATE will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

Adrian L

h/s 17/06/21.

06 days.

Supplementary: 1068.

total: 5652.40

h/s: A.B.K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle No
(Supplymentary)

SJM3061S

Hyundai Avante

QTY	Description	Condition	Repairer's Estimate(S\$)	Surveyor's Adjustment
1	RHS Front Tyre <i>included</i>		280.00	180
1	RHS Drive Shaft <i>Best.</i>		1200.00	986
1	Ball joint <i>Best</i>		150.00	77
1	Tie rod end <i>Best</i>		200.00	92
		Total Parts	1830.00	

Adrian Cj
w/s 18/06/21

1335

len 20% : 1068