

# A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113  
 HP: 8386 8989 EMAIL: atautoconsultant@gmail.com  
 Co. Reg. No. : 53368526E

Date of Estimate: 17.06.2021  
 Vehicle No: PC1028J  
 Owner: CITITRANS BUS TRANSIT PTE LTD  
 Date of Accident: 15.06.2021  
 Make & Model: KING LONG XMQ6900K  
 Chassis No : LA6R1DS80BB203980

## ESTIMATE FOR ACCIDENT VEHICLE NO PC1028J

### PARTS

1 1 Front electrical side mirror assy L/H *crn*

SUB TOTAL  
 LESS 5% *10%*  
 DISCOUNTED SUB TOTAL

~~\$2,800.00~~ *1500*  
~~\$2,800.00~~  
~~\$140.00~~ *10%*  
\$2,660.00 *1350*

### LABOUR

1 Spray painting on affected area  
 2 Wiring charges & testing commissioning  
 3 Transfer side mirror mechanism L/H

SUB TOTAL (LABOUR)

~~\$200.00~~ *150*  
~~\$120.00~~ *60*  
~~\$200.00~~ *100*  
\$520.00 *310*

SUB TOTAL (PARTS)

\$2,660.00

SUB TOTAL (LABOUR)

\$520.00

ESTIMATED GRAND TOTAL

\$3,180.00

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE OF REPAIRS, WE WOULD INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

APPROVING OFFICER SIGNATURE & COMPANY'S CHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*1350*  
*310*  


---

*1660*  
*20%*  
*1328*  
*43 - \$1,300*

*Rasul*  
*Hp 90010068*  
*1 day*  
*43*  
*22/06/21 @ 1030*  
*Resurvey after repair*