



UNITED CYCLES LLP

25, Kaki Bukit Road 4 #01-23/24/25

Synergy @ KB Singapore 417800

Tel: 6345 9060 Fax: 6345 2356

Email: united_cycles@yahoo.com

LLP Reg No: T12LL2150G

Date: 22 June 2021

LKK Auto Consultants Pte Ltd

Dear Sirs,

RE: ESTIMATE REPAIR COST FOR FBS4366U

1)	Rear Fender Bracket	\$	85.00
2)	Rear Fender	\$	48.00
3)	Cover Fender (Upper)	\$	35.00
4)	Rear License Plate Light	\$	60.00
5)	Rear Number Plate	\$	20.00
6)	Labour Charges	\$	300.00

TOTAL REPAIR COST

\$ 548.00

Yours faithfully,
United Cycles LLP

