

UNITED CYCLES LLP

25, Kaki Bukit Road 4 #01-23/24/25

Synergy @ KB Singapore 417800

Tel: 6345 9060 Fax: 6345 2356

Email: united_cycles@yahoo.com

LLP Reg No: T12LL2150G

Date: 22 June 2021

LKK Auto Consultants Pte Ltd

Dear Sirs,

RE: ESTIMATE REPAIR COST FOR FBS4366U

1)	Rear Fender Bracket	BT	\$	85.00 ✓	85
2)	Rear Fender	CRA	\$	48.00 ✓	48
3)	Cover Fender (Upper)	CRA	\$	35.00 ✓	35
4)	Rear License Plate Light	CUT	\$	60.00 ✓	60
5)	Rear Number Plate	BT	\$	20.00 15	228
6)	Labour Charges		\$	300.00 200	-10% = 205.2
TOTAL REPAIR COST			\$	548.00	\$443


\$420.2

Thruvan
82235769 23/6/21

ASm -TP not authorise
part by part repair

old parts required during after repair survey

Yours faithfully,
United Cycles LLP



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: