

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 17.06.2021
Time: 13:46:15
Page: 1

LKK - AIG (LHS) JH

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305473987
REGN NO : SHC1054C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 16.06.2021 20:30
ACCIDENT DATE : 16.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	de ✓
0002 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	fr
0003 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	?
0004 04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	?
0005 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	new ✓
0006 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	new ✓
0007 04-01-0103-0851-G	REFLECTOR/REFLEX ASSY-RR	1	32.00	20.00	25.60	cut ✓

SUB-TOTAL : 1,598.72

JOB NATURE

0000 PB	PANEL BEATING	300.00	280.
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 20-05	ADVERTISMENT STICKER-BUMPER	50.00	new ✓
0003 20-05	ADVERTISMENT STICKER-FENDER	200.00	new ✓

P.T.O

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305473987
REGN NO : SHC1054C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 16.06.2021 20:3
ACCIDENT DATE : 16.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 L REMOVE/REFIX REVERSE SENSOR

80.00 30

SUB-TOTAL : 930.00

TOTAL : 2,528.72

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanpin 97495743
up 17/6/21 4pm
2 days
LH Rising after repair
tanpin e lkhanto

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date/Time: 17.06.2021 13:38

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4090184

JC NO.: 305473987

OWNER	REGN NO.: SHC1054C	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE : HYUNDAI	FUEL
OWNER NO. 7010045	MODEL I-40	E.....1/2.....F
ADDRESS 383 SIN MING DRIVE	YR OF MANU. 29.12.2016	DATE/TIME IN 16.06.2021 20:30
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMHU097724	TARGET DATE
65508755 (R) (P)		COMPLETION DATE/TIME:
IDENTIFICATION CARD NO.		


JOB DESCRIPTION

Accident Date: 16.06.2021
NATURE: 3P 16.06.2021

S/NO

LABOR CODE

DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Signature Slip

Exit Pass

Vehicle No.: SHC1054C JU AIG

Vehicle No.: SHC1054C

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard