

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : India International Insurance Pte Ltd
 64 Cecil Street #04/#05/#06-02 ,
 IOB Building Singapore 049711

TEL: 6347 6100 FAX: 62244174/ 62257743
 ATTN: Motor Claim Department
 Your Ref No: CHENG YAP CONST PL
 Claim Type: Third Party
 Accident Date: 15/06/2021
 TP Veh Reg No: YM9136T

Estimate No: ES1700899
 Date: 15 Jun 2021
 Policy No: 5109427826-02-000002
 Veh Reg No: GBE9770B
 Make/Model: ISUZU NHR85AUE4AA
 Chassis No: JAANHR85EG7100131
 Engine No: 4JJ12L9579
 Reg. Date: 16/05/2016

Estimate Repair Cost to Vehicle No :GBE9770B

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 Rear Tipper Lower Member <i>Dented 450</i>	780.00	1 PC	780.00 450	
2 Rear Crossmember <i>Here new Len 15%: 382.50</i>	800.00	1 PC	800.00 X	
			1,580.00	
		Less 30% <i>15%</i>	474.00	1,106.00
Net Price				
3 Tail Gate Plywood <i>cracked</i>	380.00	1 PC	380.00 120 (SN)	
4 Rear Tipper Door <i>Dented</i>	2,100.00	1 PC	2,100.00 1320.	
5 Rear Tipper Side Panel - LH/RH <i>Repair</i>	1,200.00	2 PC	2,400.00 X	
6 Rear Tipper Rubber Support <i>Here new</i>	85.00	2 PC	170.00 X	
7 Rear Tipper Lock <i>Here new</i>	110.00	1 PC	110.00 X	
8 Rear Tipper Side Frame <i>Here new</i>	950.00	1 SET	950.00 X	
9 Rear Tipper Hinges <i>Bent</i>	123.00	2 PC	246.00 ✓	
10 Tail Lamp Assy - RH <i>cracked. Len 15%: 1492.60</i>	190.00	1 PC	190.00 ✓	
11 " 70 km/h " Sticker <i>? New</i>	40.00	1 PC	40.00 15 (SN)	
12 " ISUZU " Sticker <i>S-N: 280</i>	95.00	1 PC	95.00 ✓ (SN)	
13 Flammable Sticker <i>Bent</i>	40.00	1 PC	40.00 20 (SN)	
14 Number Plate	40.00	1 PC	40.00 30 (SN)	
			6,761.00	6,761.00
Labour				
15 Labour to renew & refix all above parts .	1,200.00	1 JOB	1,200.00 700.	
16 Labour to connect & rewire & renew tail lamp .	180.00	1 JOB	180.00 30	
17 To rust proofing at accident dented area .	380.00	1 JOB	380.00 100	
18 To spray & painting at accident dented area .	950.00	1 JOB	950.00 700	
			2,710.00	2,710.00
			Total	SS 10,577.00
			Add GST @ 7%	740.39
			Total Amount Payable	SS 11,317.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

TOTAL SINGAPORE DOLLAR ELEVEN THOUSAND THREE HUNDRED SEVENTEEN AND CENTS THIRTY NINE ONLY

For MAH LIAN MOTOR VEHICLE REPAIRER

total: 3685.10
 H/S: 2950
 06 Days

 AUTHORISED SIGNATURE