

(08/11/13) wef

ASS. REC. BY: Asul

REF:

C4/FCU 21006801 Rira3

B

~~000 X~~

COE XPIRY: 2025/SEP

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 89P

at Workshop m/s THINK ONE AUTOLAB

of 60, SLN LAM HUAT #02-32 (CARRIERS CTRL)

Insured: FCU

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 96K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC 89P Yr Regn: 2015 / SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: YUTONH ZK6930H AUTO c.c. 6690

Colour: MULTI A/C: Insured / Std / NI / NA

Sp.Reading: 299539 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LZYTCFD63F1021842

Gen. Cond: Good / Fair / Poor / Burnt

Steering: inorder / Jammed / Leaked / Burnt or

Brake: inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size: F: 275/70R225

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KAPSEN

Front R/Bal. 8 mm

Rear R/Bal. 8/8 mm

L/Bal. 8 mm

L/Bal. 8/8 mm

D.O.A. 14/06/21

D.O.I. 17/06/21

Survey held at THINK-ONE

Des. of Damages: Frt Rea / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 81K

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

1)

: Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to?

Transportation: _____

2)

Add Fee: : Site Insp (\$ _____)

) S + RS, SI

: Interview (\$ _____)

) Photos

: Tech. Invs (\$ _____)

) Others

: Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

ESTIMATED

PC89P YUTONG XMQ6120K

DATE 14.06.2021

| No | Qty | PARTICULAR | AMOUNT S\$ | AMOUNT S\$ |
|----|------|---|------------|------------|
| 1 | pc-2 | ROOF TOP MIRROR C/W ARM ASSY RH+LH <i>crn / LH-repair</i> | 1,420.00 | 2,840.00 |
| 2 | 1 | FRONT WINDSCREEN GLASS <i>bro</i> | | 4,855.00 |
| 3 | 2 | FRONT WINDSCREEN INNER GARNISH R+L X | 398.00 | 596.00 |
| 4 | 1 | SIDE PANEL RH <i>repair</i> | | 4,302.00 |
| 5 | 2 | DOOR PILLAR LH+LH <i>repair</i> | 788.00 | 1,576.00 |
| 6 | 1 | FRONT PANEL <i>bt</i> | | 4,885.00 |
| 7 | 1 | FRONT PANEL RE-INFORCEMENT ? | | 2,850.00 |
| 8 | 1 | FLOOR PANEL REINFORCEMENT ? | | 1,200.00 |
| 9 | 1 | FLOOR PANEL ? | | 1,500.00 |
| 10 | 1 | FRONT CHASSIS CROSS MEMBER ? | | 2,995.00 |
| 11 | 1 | DASHBOARD ASSY ? | | 3,600.00 |
| 12 | 1 | DASHBOARD RE-INFORCEMENT ? | | 655.00 |
| 13 | 1 | SPEEDO METER ASSY X | | 2,850.00 |
| 14 | 1 | FRONT PANEL KEY CYLINDER X | | 185.00 |
| 15 | 1 | FRONT PANEL GRILLE <i>crn</i> | | 621.00 |
| 16 | 1 | PANEL GRILLE LOGO <i>ne</i> | | 215.00 |
| 17 | 1 | WIPER MOTOR X | | 1,152.00 |
| 18 | 1 | WIPER LINKAGE X | | 856.00 |
| 19 | 2 | WIPER ARM <i>cut</i> | 365.00 | 730.00 |
| 20 | pc-2 | WIPER ARM COVER <i>RH-crn / LH-X</i> | 65.00 | 130.00 |
| 21 | 2 | WIPER BLADE <i>ne</i> | 198.00 | 396.00 |
| 22 | 2 | FRONT HEADLAMP HID R+L <i>RH-sca / LH-?</i> | 3,250.00 | 6,500.00 |
| 23 | 2 | FRONT HEADLAMP PANEL R+L ? | 285.00 | 570.00 |
| 24 | 1 | TOW HOOK ? | | 425.00 |
| 25 | 1 | FRONT BUMPER <i>de</i> | | 3,202.00 |
| 26 | 2 | FRONT BUMPER FOG LAMP R+L <i>RH-? / LH-X</i> | 425.00 | 850.00 |
| 27 | 1 | FRONT BUMPER NUMBER PLATE BASE <i>bt</i> | | 220.00 |
| 28 | 1 | FRONT BUMPER RE-INFORCEMENT ? | | 952.00 |
| 29 | 1 | FRONT WIRE HARNESS TO FUSE BOX X | | 1,552.00 |
| 30 | 1 | FRONT AUTO DOOR LH <i>repair</i> | | 4,720.00 |
| 31 | 4 | FRONT AUTO DOOR LOCK CATCH X | 80.00 | 320.00 |
| 32 | 1 | FRONT AUTO DOOR LOWER ARM <i>bro</i> | | 799.00 |
| 33 | 1 | FRONT AUTO DOOR MOTOR X | | 1,855.00 |
| 34 | 1 | FOOT STEP BOARD LH <i>repair</i> | | 350.00 |
| 35 | 1 | REAR WINDSCREEN GLASS PANEL <i>de</i> | | 2,422.00 |
| 36 | 1 | TAIL GATE <i>bt</i> | | 4,850.00 |
| 37 | 2 | TAIL GATE DAMPER R+L X | 190.00 | 380.00 |
| 38 | 2 | TAIL GATE HINGE R+L X | 85.00 | 170.00 |
| 39 | 2 | TAIL GATE RUBBER STOPPER <i>rec</i> | 15.00 | 30.00 |
| 40 | 2 | TAIL GATE LOCK KEY CYLINDER X | 115.00 | 230.00 |
| 41 | 1 | TAIL GATE (ZK6930H) EMBLEM <i>rec</i> | | 253.00 |
| 42 | 1 | TAIL GATE (YUTONG) EMBLEM <i>rec</i> | | 255.00 |
| 43 | 1 | TAIL GATE PULL HANDLE X | | 45.00 |
| 44 | 1 | SIDE ENGINE COMPARTMENT REAR DOOR RH <i>repair</i> | | 1,445.00 |
| 45 | 2 | SIDE ENGINE COMPARTMENT REAR DOOR LOCK X | 65.00 | 130.00 |
| 46 | 2 | TAIL LAMP R+L <i>LH-? / RH-crn</i> | 825.00 | 1,650.00 |
| 47 | 1 | REAR CORNER PANEL RH <i>bro</i> | | 4,832.00 |
| 48 | 1 | REAR CORNER PANEL LAMP RH <i>crn</i> | | 115.00 |
| 49 | 1 | REAR CORNER PANEL INNER SUPPORT BRACKET ? | | 350.00 |
| 50 | 1 | REAR REFLECTOR <i>crn</i> | | 450.00 |
| 51 | 1 | REAR BUMPER <i>de</i> | | 2,566.00 |
| 52 | 1 | NUMBER PLATE LED LAMP <i>crn</i> | | 185.00 |
| 53 | 1 | REAR BUMPER RE-INFORCEMENT ? | | 890.00 |
| 54 | 1 | REVERSE SENSOR WIRE HARNESS X | | 85.00 |

| | | | | |
|----------|---|-------------------------------------|-------|---------------|
| 55 | 1 | REAR CHASSIS CROSS MEMBER | | 980.00 |
| 56 | 1 | FUEL FILTER FEED PUMP ASSY | | 650.00 |
| 57 | 1 | ENGINE CRANKSHAFT PULLEY | | 1,855.00 |
| 58 | 1 | ENGINE CRANKSHAFT PULLEY OIL SEAL | | 85.00 |
| 59 | 1 | ENGINE FAN BELT | | 188.00 |
| 60 | 1 | RADIATOR ASSY | | 2,995.00 |
| 61 | 1 | RADIATOR FAN BLADE | | 455.00 |
| 62 | 1 | FAN BLADE ROTOR ASSY | | 652.00 |
| 63 | 1 | RADIATOR FAN BELT | 45.00 | 90.00 |
| 64 | 1 | RADIATOR FAN BELT TENSIONER ASSY | | 355.00 |
| 65 | 1 | RADIATOR FAN BELT TENSIONER BRACKET | | 452.00 |
| 66 | 1 | ENGINE FAN BELT TENSIONER BEARING | | 482.00 |
| 67 | 2 | AIR CON COMPRESSOR BELT | 45.00 | 90.00 |
| 68 | 1 | ENGINE ASSY | | 38,000.00 |
| | | | | \$ 129,966.00 |
| LESS 10% | | | | \$ 12,996.60 |
| | | | | \$ 116,969.40 |

| No | Qty | PARTICULAR | SPECAIL NETT ITEM | AMOUNT \$\$ |
|----|-----|-------------------------------------|-------------------|-----------------------|
| 1 | 1 | FRONT WINDSCREEN GLASS SEALANT/SEAL | Neu | 520.00 350 |
| 2 | 1 | REAR WINDSCREEN GLASS SEALANT/SEAL | Neu | 450.00 280 |
| 3 | 4 | PANEL JOINT SEAL | Neu | 120.00 480.00 350 |
| 4 | 2 | NUMBER PLATE FRONT & REAR | Ch | 100.00 70 |
| 5 | 1 | FRONT PANEL STICKER (ORIGINAL) | Neu | 550.00 300 |
| 6 | 1 | REAR PANEL STICKER (ORIGINAL) | Neu | 550.00 300 |
| 7 | 1 | TAIL GATE 60KM/H STICKER | Neu | 15.00 10 |
| 8 | 1 | ERP BRACKET | Neu | 25.00 |
| 9 | 4 | REVERSE SENSOR | X | 100.00 400.00 X |
| 10 | 1 | REAR WINDSCREEN GLASS PANEL LOGO | Neu | 220.00 80 |
| | | | | \$ 3,320.00 |

LABOUR & MISCELLANEOUS:

AMOUNT \$\$

| | | | |
|---|--|--------|--------------------------|
| 1 | To remove damaged front/rear body parts with all necessary components/ attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments | * 3900 | 18,000.00 ? |
| 2 | To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials | 2800 | 5,000.00 |
| 3 | To remove,refix dashboard panel,compartment side board,upholstery, inner garnishes with all necessary components/attachments | 300 | 500.00 |
| 4 | To remove,refix front windscreen glass and water test | * 300? | 1,500.00 |
| 5 | To remove,refix rear windscreen glass and water test | * 300? | 1,000.00 |
| 6 | To remove,refix rear side panel glass | 250 | 500.00 |
| 7 | To remove,replace radiator,fan blade rotor with all necessary components | 100 | 280.00 photo? |
| 8 | To remove,replace engine crankshaft pulley with all necessary components/attachments | 100? | 280.00 photo? |
| 9 | To check reset engine diagnosis system code | X | 200.00 |

| | | |
|----|--|------------------------------|
| 10 | To conduct front headlamp alignment | 50.00 30 |
| 11 | To install reverse sensor with all necessary components | 100.00 X |
| 12 | Towing from accident scene to carros centre <i>receipt (1 trip)</i> | 250.00 ? |
| 13 | To remove,replace new engine with all necessary components/attachments | <u>1,200.00</u> X |
| | | \$ 28,830.00 |
| | | <hr/> |
| | | \$ 116,969.40 |
| | | 3,320.00 |
| | | <u>28,830.00</u> |
| | | \$ 149,119.40 |

Rasul
Hp 90010068
20 days
L/S
17/06/21 @ 1400
Resy after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|---|
| Date of Submission | 15/06/2021 17:04 (SGT) |
| Date of Accident | 14/06/2021 08:10 (SGT) |
| Exact Location of Accident | Near 2 Corporation Rd, Singapore 618494 |
| Additional Location Information | ALONG CORPORATION FLYOVER |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-----------------------------|
| Vehicle Registration Number | PC89P |
| INSURED/POLICYHOLDER | |
| Is company? | Yes |
| Name Of Registered Owner | BRICKSTON TRANSPORT SERVICE |
| Company Reg No | 4XXXX000X |
| Email Address | oswagan@brickston.com.sg |
| Mobile Phone No | (Phone) +65-86884949 |
| Alternative Phone No | (Office) +65-65588088 |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | Yutong |
| Model | Zk6930h |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | Employment |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Bus |
| Transmission | Auto |
| CC | 6690 |

INSURANCE COMPANY

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC Income Insurance Co-operative Ltd |
| Type of Coverage | Comprehensive |
| Fleet Policy | No |
| Policy Number | 5108172073-02-000001 |
| Cover Note Number | - |

DRIVER

| | |
|----------------|------------------------------|
| Name of Driver | ABDUL RAHMAN BIN MOHAMED ALI |
| NRIC No | SXXXX390I |

| | |
|--|----------------------------|
| Date Of Birth | 28/08/1955 |
| Occupation | Outdoor |
| Date Of Driving Pass | 12/06/1981 |
| Driving experience | 40 YEARS |
| Gender | Male |
| Mobile Number | (Phone) +65-92372344 |
| Alt. Phone Number | - |
| Email Address | oswagan@brickston.com.sg |
| Address | BLK 705 CLEMENTI WEST ST 2 |
| Address complement | #04-237 |
| Postcode | 120705 |
| Is the driver the policyholder? | No |
| If No, Relationship of the Driver with the Insured | Employee |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|-----------------|
| Type of Accident | Chain Collision |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 5 |
| Was anybody injured in the Accident? | Yes |
| Was any injured conveyed to hospital by ambulance? | No |
| Was any other material or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |

DETAILS OF POLICE ACTION

| | |
|---|--------------------------------------|
| Was the accident reported to the police? | Yes |
| Police Station Name | Clementi Neighbourhood Police Centre |
| Police Station Phone No | (Phone) +65-18008729999 |
| Alt. Police Station Phone No | (Fax) +65-68728039 |
| Police Station Address | No. Singapore 129858 |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ON THE MOST LEFT LANE, BEFORE CORPORATION FLYOVER, FRONT VEHICLE JAM BRAKE AND COME TO A COMPLETE STOP, I MANAGE TO STOP MY BUS ALSO, A MOMENT LATER I GOT REAR ENDED BY A LORRY, WHEN I WENT DOWN TO CHECK I DISCOVER THAT THERE IS FEW MORE VEHICLES INVOLVED IN THIS ACCIDENT. I WAS THE SECODN VEHICLES IN THIS CHAIN COLLISION, I ONLY MANAGE TO RECORD THE FRONT AND THE BACK OF MY BUS VEHICLE NUMBER.

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | Yes |
| Was there any audio recorded? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------|
| Vehicle Registration Number | YP559A |
| Vehicle Manufacturer | - |
| Vehicle Model | - |

| | |
|---|--------------------|
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|---|--------------------|
| Vehicle Registration Number | YP9890H |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

DETAILS OF OTHER VEHICLE PROPERTY 3

| | |
|---|--------------------|
| Vehicle Registration Number | UNKNOWN |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

DETAILS OF OTHER VEHICLE PROPERTY 4

| | |
|---|---------|
| Vehicle Registration Number | UNKNOWN |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Bus |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |

INJURED PERSONS DETAILS

INJURED 1

| | |
|---|------------------------------|
| Name of injured person | ABDUL RAHMAN BIN MOHAMED ALI |
| Address | BLK 705 CLEMENTI WEST ST 2 |
| Address Complement | #04-237 |
| Post Code | 120705 |
| Approximate Age Years Old | - |
| Injuries Sustained | - |
| Injured person in which vehicle? | PC89P |
| Were seat belts worn? | Yes |
| Was this injured conveyed to hospital by ambulance? | No |

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

BRICKSTON TRANSPORT SERVICE
[Signature]


Policyholder's Signature / Date & Time
14/6/2021

Sketch Plan @ 1400

[Signature]
Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel
Chang Che Sing
Sketch Form

- A = PC 89P
- B = YP 559 A
- C = YP 9890H
- D = Unknown
- E = Unknown



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------|-------------------------|
| Owner ID Type: | Business |
| Owner ID: | 000X |
| Vehicle No.: | PC89P |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 24 Jun 2021 |
| Vehicle Make: | YUTONG |
| Vehicle Model: | ZK6930H AUTO |
| Primary Colour: | Multicolor |
| Manufacturing Year: | 2015 |
| Engine No.: | ISB67E525022139261 |
| Chassis No.: | LZYTCID83F1021842 |
| Maximum Power Output: | |
| Open Market Value: | \$110,609.00 |
| Original Registration Date: | 03 Sep 2015 |
| First Registration Date: | 03 Sep 2015 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$5,531.00 |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | |
| PARF Rebate Amount: | \$0.00 |
| COE Expiry Date: | 02 Sep 2025 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| PQP Paid: | \$32,194.00 |
| COE Rebate Amount: | \$14,038.00 |
| Total Rebate Amount: | \$14,038.00 |

The information contained herein is correct as at 24 Jun 2021

OK

Yutong ZK6938H

[Overview](#)

[Financial](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)

Price **\$133,000** **Lifespan** 19-Apr-2037

Depreciation \$22,840 /yr
View models with similar depre **Reg Date** 20-Apr-2017

Mileage N.A. **Manufactured** 2016

Road Tax N.A. **Transmission** Auto

Dereg Value N.A. **Fuel Type** Diesel

COE N.A. **OMV** \$101,220

Engine Cap 6,690 cc **ARF** \$5,061

Curb Weight 9,880 kg **No. of Owners** 1

Type of Vehicle Bus/Mini Bus

Features

Stock Features.

