

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21006807/ARS3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100501796
<b>Claimant Vehicle No :</b>	SCU9577Y	<b>Insured Vehicle No :</b>	SLL5890J
Date of Loss:	12/06/2021	Nature of Claim:	TP
		Claim No:	8197491360SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SCU9577Y</b>	Engine No:	40785309B38B15A
Make & Model:	BMW 118i, 1.5 (A)	Chassis No:	WBA1R520X05C81232
Reg. Date:	31/05/2018 (Man. Year: 2018)	Odometer:	26585 km
Colour:	Orange		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,392.00	1,557.00	4,835.00	75.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,732.00	2,672.00	2,060.00	43.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,124.00</b>	<b>4,229.00</b>	<b>6,895.00</b>	<b>61.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	778.68	296.03	482.65	61.98
<b>Nett Amount (S\$)</b>	<b>11,902.68</b>	<b>4,525.03</b>	<b>7,377.65</b>	<b>61.98</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>5,227.03</b>		

INSPECTION

Date of Assignment:	16/06/2021		
Date Inspected:	16/06/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER EMBLEM SPORT LINE-LH	Necessary	81.00 FS	*81.00 FS
2	1		*FRONT WING MIRROR MOUNTING -LH	Cut	1,476.00 FS	*1,476.00 FS
3	1		*FRONT WING MIRROR CAP -LH	Not Necessary	144.00 FS	*- FS
4	1		*FRONT WING MIRROR GLASS -LH	Not Necessary	720.00 FS	*- FS
5	1		*REAR BUMPER	Repair	1,836.00 FS	*- FS
6	1		*REAR BUMPER GUIDE -LH	Not Necessary	225.00 FS	*- FS
7	1		*REAR WHEEL RIM -LH	Not Necessary	1,710.00 FS	*- FS
8	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>6,392.00      1,557.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY & FRONT PARKING AID	New	280.00	0.00
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRM TO FACILITATE RENEWAL OF LHS WING MIRROR ASSY	New	280.00	280.00
3	TO REMOVE AND REINSTALL REAR BUMPER .TO REPAIR LHS FRONT FENDER AND LHS REAR FENDER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL PARTS REMOVED	New	1,200.00	600.00
4	TO RESPRAY REAR BUMPER ,LHS REAR FENDER ,LHS FRONT FENDER ,LHS FRONT DOOR AND LHS WING MIRROR COVER	New	2,500.00	1,600.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,732.00</b>	<b>2,672.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >