

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0487/2021/GW
DATE : 15-Jun-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 6/5/2021

YOUR INSURED VEH NO : SLL 5890 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LEONG KWONG CHEE
ADDRESS : BLK 59, TELOK BLANGAH
HEIGHTS, #04-07
SINGAPORE 100059
TELEPHONE : HP +65 90210473
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10537940R00
VEHICLE NO : **SCU 9577 Y**
MODEL CODE : BMW 118I 5DR LED 16'-17'
MODEL YEAR : 31/5/2018
ENGINE NO : 40785309B38B15A
CHASSIS NO : WBA1R520X05C81232
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Jun-21
PLACE OF ACCIDENT : ENTRANCE VIVOCITY BASEMENT CAR PARK BESIDE
HARBOURFRONT

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCU 9577 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY & FRONT PARKING AID.	S/N \$ 280.00 X.	
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM TO FACILLITATE RENEWAL OF LHS WING MIRROR ASSY.	S/N \$ 280.00 ✓	
3	TO REMOVE AND REINSTALL REAR BUMPER. TO REPAIR LHS FRONT FENDER AND LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED.	\$ 1,200.00 600.	
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS WING MIRROR COVER.	\$ 2,500.00 1600.	
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 X.	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,732.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCU 9577 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER EMBLEM ' SPORT LINE ' - LH <i>new</i>	1	\$ 81.00	✓
2	FRONT WING MIRROR MOUNTING-LH <i>let</i>	1	\$ 1,476.00	✓
3	FRONT WING MIRROR CAP-LH <i>new</i>	1	\$ 144.00	+
4	FRONT WING MIRROR GLASS-LH <i>new</i>	1	\$ 720.00	+
5	REAR BUMPER <i>new</i>	1	\$ 1,836.00	+
6	REAR BUMPER GUIDE-LH <i>new</i>	1	\$ 225.00	+
7	REAR WHEEL RIM-LH <i>new</i>	1	\$ 1,710.00	+
8	SUNDRIES		\$ 200.00	.
TOTAL SPARE PARTS		:	\$ 6,392.00	
TOTAL LABOUR CHARGES		:	\$ 4,732.00	
GRAND TOTAL		:	\$ 11,124.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King,*
SURVEYED DATE : *16/06/21.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not authorised. 06 days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT