



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 03/05/2021

ESTIMATE

NO : QUOT202105-000037(00)

DATE : 17/06/2021

POLICY NO : 999995580

VEH REG NO : SMG2469C

MAKE/MODEL : MERCEDES BENZ A200 COMPT
SALN PROGRESSIVE (R18
LED)

CHASSIS NO : WDD1770872J037805

ENGINE NO : 28291480027612

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMG2469C

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Rear bumper <i>Denton</i>	1	880.00	880.00 ✓
2 Rear bumper side retainer - RH <i>SN</i>	1	78.00	78.00 X
3 Rear bumper reinforcement <i>2 1st Denton</i>	1	410.00	410.00 ✓ ✓
4 Rear bumper reflector - RH <i>7 mounting brace</i>	1	48.00	48.00 ✓ ✓
5 Rear bumper sensor <i>Dent</i>	1	138.00	138.00 ✓
6 Rear bumper sensor seals <i>Hue</i>	6	8.00	48.00 ✓
7 Rear bumper clips <i>Hue</i>	15	5.50	82.50 ✓
			1,684.50
		Add 10%	168.45
			1,852.95
LABOUR			
8 To panel beat & repair RH rear chassis frame, including replacement of parts and align where necessary to refit and adjust the same	1	800.00	800.00 400/-
9 To remove and refit rear bumper sensor	1	100.00	100.00 40/-
10 To check and rectify wiring system	1	80.00	80.00 30/-
11 To putty and spray on affected areas	1	800.00	800.00 400/-
			1,780.00
		TOTAL	S\$ 3,632.95
		ADD GST @ 7%	254.31
		GRAND TOTAL	S\$ 3,887.26

SINGAPORE DOLLAR THREE THOUSAND EIGHT HUNDRED EIGHTY-SEVEN AND CENTS TWENTY-SIX ONLY

18/06/2021 @ 1430hrs

Not Authorized

Part by Part

3 days

97237799

Photo after repair with damaged parts

Excess T&A

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE