



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

KELVIN CHIA PARTNERSHIP

Ref: CS/CTI19012762/Dtf3e2-1

6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC
TOWER FOUR SINGAPORE 038986

Date: 30/07/2021

Code: L041

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	GBD 1148G	Veh. Inspected	GBF 7473S
Policy No.		Coverage (\$)	0.00
Claim No.	SS/JL/YX/sm/2020001184	Excess (\$)	0.00
Assign From	TEO YI XUAN	Assign Date	17/06/2021

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JN1SC2F24Z0859270	Colour	GOLD
Odometer	73831 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	YOKOHAMA	5 mm
L/H Front Tyre	195 R15C	YOKOHAMA	5 mm
R/H Rear Tyre	155 R13 (D)	YOKOHAMA	5/5 mm
L/H Rear Tyre	155 R13 (D)	YOKOHAMA	5/5 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	13/07/2019	Inspection Date	25/06/2021
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------