



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2104615

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 01/07/2021
Reference CS3/GRB21006811/Vtf3e2
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 8974H
Insured Veh. SLU 5300Z
Claim No. MFL2021D0002557
Policy No. D21MFL0000447
Accident Date 14/06/2021
Inspection Date 18/06/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 18.06.2021 11.30am	
- Dismantle Inspection 18.06.2021 02.00pm	
- After Repair Inspection 23.06.2021 03.17pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM