

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006818/T1PA3Q2
Date: 25/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800149049
Claimant Vehicle No :	SHD7295D	Insured Vehicle No :	SJE3277D
Date of Loss:	17/06/2021	Nature of Claim:	TP
		Claim No:	4807079446SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD7295D		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B82333
Reg. Date:	06/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU103077540
Colour:	Blue	Odometer:	354965 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,475.10	824.90	1,650.20	66.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	630.00	650.00	50.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,755.10	1,454.90	2,300.20	61.26
+ GST 7.00/7.00% (S\$)	262.86	101.84	161.02	61.26

Nett Amount (S\$)	4,017.96	1,556.74	2,461.22	61.26
+ Loss of Use (3.5 x S\$50.00/day) (S\$)		175.00		
+ Car Rental (3.5 x S\$126.47/day) (S\$)		442.65		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,176.39		
Global Sum Settlement (S\$)		2,100.00		

INSPECTION

Date of Assignment: 18/06/2021

Date Inspected: 18/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR UNDER COVER	Deformed	552.60 FL	*552.60 FL
3	1		*REAR REINFORCEMENT	Not Necessary	318.80 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	225.40 FL	*- FL
5	1		*REAR TOWING COVER	Not Necessary	82.70 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*LH TAIL UPPER LAMP	Not Necessary	557.90 FL	*- FL
8	1		*LH TAIL LOWER LAMP	Not Necessary	548.40 FL	*- FL
9	1		*REAR TRUNK TOYOTA EMBLEM	Not Necessary	47.00 FL	*- FL
10	1		*REAR TRUNK PRIUS	Not Necessary	52.90 FL	*- FL
11	1		*REAR TRUNK HYBIRD	Not Necessary	52.90 FL	*- FL
12	1		*BOOTLID COMFORT LOGO /TEL NUMBER	Not Necessary	60.00 FS	*- FS
13	1		*BOOTLID COMFORT APP	Not Necessary	40.00 FS	*- FS
14	1		*BUMPER MAT	Necessary	50.00 FS	*50.00 FS
15	1		*REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
					Sub Total (S\$)	3,204.90
					- List Item Discount on L Items 25.00/25.00% (S\$)	729.80
					Total Parts (S\$)	2,475.10
						824.90

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	350.00
2	SPRAY PAINTING CHARGE	New	600.00	250.00
3	TUFF KOTE	New	60.00	0.00
4	CHECK LIGHTING	New	60.00	0.00
5	REMOVE AND REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (S\$)			1,280.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >