



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16
 Singapore 079120

Estimate No: **ES2100057**
 Date: 17 Jun 2021
 Policy No:
 Veh Reg No: **SLU4132Z**
 Make/Model: **FORD FOCUS SW
 TITANIUM 1.6 TI-VCT
 A/T**
 Chassis No: **WF06XXGCC6FY77658**
 Engine No: **FY77658**
 Reg. Date: 27/08/2015

ATTN: Motor Claim Department

*Not Notch in
 11 Pny @ 3000/-
 Penny After Paint*

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 16/06/2021
 TP Veh Reg No: SFP3188S

4 days

Estimate Repair Cost to Vehicle No :SLU4132Z

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00	X
2 REVERSE SENSOR CORNER - LH	395.20	1 PC	395.20	X
3 REVERSE SENSOR CORNER - RH	395.20	1 PC	395.20	X
4 REVERSE SENSOR CENTRE - LH	395.20	1 PC	395.20	X
5 REVERSE SENSOR CENTRE - RH	395.20	1 PC	395.20	X
			1,640.80	1,640.80
Spare Parts				
6 REAR BOOT LID	2,206.10	1 PC	2,206.10	X
7 REAR BOOT LID WEATHERSTRIP	235.90	1 PC	235.90	X
8 REAR BOOT LID LOCK	455.90	1 PC	455.90	X
9 REAR BOOT LID 'TITANIUM' EMBLEM	125.60	1 PC	125.60	X
10 REAR BOOT LID 'FOCUS' EMBLEM	105.10	1 PC	105.10	X
11 REAR BUMPER	1,810.20	1 PC	1,810.20	X
12 REAR BUMPER REINFORCEMENT	740.10	1 PC	740.10	X
13 REAR BUMPER REFLECTOR - LH	128.50	1 PC	128.50	X
14 REAR BUMPER REFLECTOR - RH	128.50	1 PC	128.50	X
15 REAR BUMPER BRACKET - LH	132.20	1 PC	132.20	X
16 REAR BUMPER BRACKET - RH	132.20	1 PC	132.20	X
17 REAR END PANEL	295.00	1 PC	295.00	X
18 REAR END PANEL TOP GARNISH	253.00	1 PC	253.00	X
19 REAR EXHAUST MUFFLER	2,840.40	1 PC	2,840.40	X
20 REAR BOOT LID NUMBER PLATE GARNISH	665.50	1 PC	665.50	X
21 REAR BUMPER TOWING COVER	85.50	1 PC	85.50	X
22 REAR BUMPER INNER IMPACT GARNISH	198.20	1 PC	198.20	X
23 REAR TAILLAMP LOWER GARNISH - LH	295.00	1 PC	295.00	X
24 REAR TAILLAMP LOWER GARNISH - RH	295.00	1 PC	295.00	X
			11,127.90	11,127.90
Labour				
25 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,500.00	1 JOB	1,500.00	4500
26 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	4000
27 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00	X
28 TO REMOVE/RENEW EXHAUST MUFFLER.	250.00	1 JOB	250.00	X

*261.50
 261.50*

short

20%

*1310
 650+0*

581

20%



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 16/06/2021
TP Veh Reg No: SFP3188S

Estimate No: ES2100057
Date: 17 Jun 2021
Policy No:
Veh Reg No: SLU4132Z
Make/Model: FORD FOCUS SW
TITANIUM 1.6 TI-VCT
A/T
Chassis No: WF06XXGCC6FY77658
Engine No: FY77658
Reg. Date: 27/08/2015

Estimate Repair Cost to Vehicle No :SLU4132Z

Description	U/Price	Quantity	List Price	Amount
29 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	15/
30 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	80.00	1 PC	80.00	x
31 COMPUTER DIAGNOSTIC RESET.	280.00	1 PC	280.00	x
			3,810.00	3,810.00
			Total	SS 16,578.70
			Add GST @ 7%	1,160.51
			Total Amount Payable	SS 17,739.21

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND SEVEN HUNDRED THIRTY NINE AND CENTS TWENTY ONE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteLtd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 16/06/2021
TP Veh Reg No: SFP3188S

Estimate No: ES2100057
Date: 22 Jun 2021
Policy No:
Veh Reg No: SLU4132Z
Make/Model: FORD FOCUS SW
TITANIUM 1.6 TI-VCT
A/T
Chassis No: WF06XXGCC6FY77658
Engine No: FY77658
Reg. Date: 27/08/2015

Estimate Repair Cost to Vehicle No :SLU4132Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
Spare Parts				
1 REVERSE SENSOR HOLDER CENTRE LH	68.00	1 PC	68.00	✓
2 REVERSE SENSOR HOLDER CENTRE RH	68.00	1 PC	68.00	✓
			136.00	136.00
			Total	S\$ 136.00
			GST Amount	S\$ 9.52
			Total Amount Payable	S\$ 145.52

2.06

For Yee Auto Pte Ltd



AUTHORISED SIGNATURE