



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21006824/R1vf3e2 Date: 10/08/2021 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SLQ 6950L	
	Policy No. Z20VP05027106	Coverage (\$)	0.00	
	Claim No. 20/21/21/VP05/024657	Excess (\$)	4,500.00	
	Assign From GERALD POH	Assign Date	18/06/2021	
2. Vehicle Particulars & Condition				
	Make & Model TOYOTA HARRIER PREMIUM 2.0 A	c.c	1986	
	Engine No. HIDDEN	Year of Reg.	2017	
	Chassis No. ZSU600083691	Colour	GREY	
	Odometer 39689 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	SPORTS RIM	
	General FAIR			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 13/06/2021	Inspection Date	18/06/2021	
	Survey held at MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
	A) THE MARKET VALUE IS S\$98,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	