

Estimate

15/06/2021

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Page # :- 1
Veh # :- SLQ6950L
Veh Model :- TOYOTA HARRIER
Estimate# :- CK421959
Claim # :-
ACC. Date :- 13/06/21
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Attention :- XA025

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT DOOR LH <i>buc</i>	1 PC	650.00	650.00
2.	FRONT DOOR PROTECTOR LH <i>cm</i>	1 PC	75.00	75.00
3.	FRONT DOOR RUBBER LH <i>ne</i>	1 PC	90.00	90.00
4.	FRONT DOOR LOWER RUBBER LH <i>ne</i>	1 PC	40.00	40.00
5.	FRONT DOOR BLACK TAPE LH <i>ne</i>	5 PC	40.00	200.00
6.	FRONT DOOR LOCK <i>? bt</i>	1 PC	250.00	250.00
7.	FRONT DOOR CATCH LH <i>x sue</i>	1 PC	35.00	35.00 X
8.	REAR DOOR LH <i>buc</i>	1 PC	650.00	650.00
9.	REAR DOOR PROTECTOR LH <i>cm</i>	1 PC	80.00	80.00
10.	REAR DOOR RUBBER LH <i>ne</i>	1 PC	90.00	90.00
11.	REAR DOOR LOWER RUBBER LH <i>ne</i>	1 PC	46.00	46.00
12.	REAR DOOR BLACK TAPE LH <i>ne</i>	5 PC	40.00	200.00
13.	REAR DOOR LOCK <i>? bt</i>	1 PC	260.00	260.00
14.	REAR DOOR CATCH <i>x sue</i>	1 PC	35.00	35.00 X
15.	REAR DOOR OUTER MOULDING LH <i>? cm</i>	1 PC	75.00	75.00
16.	REAR DOOR HINGE LH <i>? bt</i>	2 PC	48.00	96.00
17.	REAR FENDER 1/4 GLASS C/W MOULDING LH <i>cut</i>	1 PC	390.00	390.00
18.	REAR FENDER 1/4 GLASS SEALANT <i>sn</i>	1 PC	40.00	40.00
19.	ROCKER GARNISH LH <i>Turn</i>	1 PC	390.00	390.00
20.	ROCKER GARNISH CLIPS <i>ne</i>	10 PC	5.00	50.00
21.	ROCKER PANEL LH <i>repair</i>	1 PC	300.00	300.00 X
22.	ROCKER PANEL TOP GARNISH LH <i>? x sue</i>	2 PC	75.00	150.00 X
23.	CENTRE PILLAR LH <i>bt</i>	1 PC	300.00	300.00
24.	CENTRE PILLAR INNER MEMBER LH <i>repair</i>	1 PC	250.00	250.00 X
25.	FLOOR PANEL - REPAIR	1 PC		
26.	REAR FENDER LH - REPAIR	1 PC		
LIST TOTAL S\$				4,742.00
15% COST PLUS S\$				711.30
				5,453.30

LABOUR :

TO CUT & WELD CENTRE PILLAR LH, CENTRE INNER MEMBER LH, ROCKER PANEL LH, TO REPAIR LH FLOOR PANEL, REAR FENDER LH. TO REMOVE & REFIT DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS

TO SPRAY AFFECTED AREAS

TO REMOVE & REFIX DOOR MECHANISM, TRANSFER DOOR POWER WINDOW, CHECK & TEST POWER WINDOW AND CENTRE LOCKING SYSTEM

TO REMOVE & REFIX SAFETY BELT, REAR CUSHION CARPET AND OTHER ATTACHMENT PARTS

TO PROGRAMMING ADAS SYSTEM

TO REMOVE & REFIX ROOF LILING, FRONT CUSHION

900 1,400.00

800 1,200.00

80 160.00

60 120.00

100 200.00

3852
+ 1590
4429.80

S/N-40

5/sep

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

5/06/2021

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 141268

Veh # :- SLQ6950L

Veh Model :- TOYOTA HARRIER

Estimate# :- CK421959

Claim # :-

ACC. Date :- 13/06/21

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	& SAFETY BELT			100 150.00
	LABOUR TOTAL S\$	2040		3,230.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,683.30

GST @ 7 % 607.83

AMOUNT DUE S\$ 9,291.13

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary work to be resurveyed and is subject to final approval by the Company

Acknowledged:
Signature:
Date:

4429.80
401.00
2040.00
6509.80

Hp 90010068

9 days

1/5 P/P

18/06/21 @ 1600

Resy after repair

EXCESS: TBA

Revert