

Main Office:

Mova Building,
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

15/06/2021

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Page # : 1

Veh # : SLQ6950L

Veh Model : TOYOTA HARRIER

Estimate# : CK421959

Claim # :

ACC. Date : 13/06/21

Terms : C.O.D Days

Remarks :

Attention :- XA025

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT DOOR LH <i>buc</i>	1	PC 650.00	650.00
2.	FRONT DOOR PROTECTOR LH <i>can</i>	1	PC 75.00	75.00
3.	FRONT DOOR RUBBER LH <i>nee</i>	1	PC 90.00	90.00
4.	FRONT DOOR LOWER RUBBER LH <i>nee</i>	1	PC 40.00	40.00
5.	FRONT DOOR BLACK TAPE LH <i>nee</i>	5	PC 40.00	200.00
6.	FRONT DOOR LOCK <i>? bt</i>	1	PC 250.00	250.00
7.	FRONT DOOR CATCH LH <i>X</i>	1	PC 35.00	35.00
8.	REAR DOOR LH <i>buc</i>	1	PC 650.00	650.00
9.	REAR DOOR PROTECTOR LH <i>can</i>	1	PC 80.00	80.00
10.	REAR DOOR RUBBER LH <i>nee</i>	1	PC 90.00	90.00
11.	REAR DOOR LOWER RUBBER LH <i>nee</i>	1	PC 46.00	46.00
12.	REAR DOOR BLACK TAPE LH <i>nee</i>	5	PC 40.00	200.00
13.	REAR DOOR LOCK <i>? bt</i>	1	PC 260.00	260.00
14.	REAR DOOR CATCH <i>X</i>	1	PC 35.00	35.00
15.	REAR DOOR OUTER MOULDING LH <i>? can</i>	1	PC 75.00	75.00
16.	REAR DOOR HINGE LH <i>? ? bt</i>	2	PC 48.00	96.00
17.	REAR FENDER 1/4 GLASS C/W MOULDING LH <i>cut</i>	1	PC 390.00	390.00
18.	REAR FENDER 1/4 GLASS SEALANT <i>nee</i>	1	PC 40.00	40.00
19.	ROCKER GARNISH LH <i>to be</i>	1	PC 390.00	390.00
20.	ROCKER GARNISH CLIPS <i>nee</i>	10	PC 5.00	50.00
21.	ROCKER PANEL LH <i>repair</i>	1	PC 300.00	300.00
22.	ROCKER PANEL TOP GARNISH LH <i>? X</i>	2	PC 75.00	150.00
23.	CENTRE PILLAR LH <i>bt</i>	1	PC 300.00	300.00
24.	CENTRE PILLAR INNER MEMBER LH <i>repair</i>	1	PC 250.00	250.00
25.	FLOOR PANEL - REPAIR	1	PC	
26.	REAR FENDER LH - REPAIR	1	PC	
LIST TOTAL S\$				4,742.00
15% COST PLUS S\$				711.30
				5,453.30

LABOUR :

TO CUT & WELD CENTRE PILLAR LH, CENTRE INNER MEMBER LH, ROCKER PANEL LH, TO REPAIR LH FLOOR PANEL, REAR FENDER LH. TO REMOVE & REFIT DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS

TO SPRAY AFFECTED AREAS

TO REMOVE & REFIX DOOR MECHANISM, TRANSFER DOOR POWER WINDOW, CHECK & TEST POWER WINDOW AND CENTRE LOCKING SYSTEM

TO REMOVE & REFIX SAFETY BELT, REAR CUSHION CARPET AND OTHER ATTACHMENT PARTS

TO PROGRAMMING ADAS SYSTEM

TO REMOVE & REFIX ROOF LILING, FRONT CUSHION

900 ~~1,400.00~~

800 ~~1,200.00~~

80 ~~160.00~~

60 ~~120.00~~

100 ~~200.00~~