

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

15/06/2021

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # - 1

Veh # - SLQ6950L

Veh Model - TOYOTA HARRIER

Estimate# - CK421959

Claim # -

ACC. Date - 13/06/21

Terms - C.O.D Days

Remarks -

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :				
1.	FRONT DOOR LH <i>bu</i>	1	PC	650.00
2.	FRONT DOOR PROTECTOR LH <i>cm</i>	1	PC	75.00
3.	FRONT DOOR RUBBER LH <i>ne</i>	1	PC	90.00
4.	FRONT DOOR LOWER RUBBER LH <i>ne</i>	1	PC	40.00
5.	FRONT DOOR BLACK TAPE LH <i>ne</i>	3	PC	40.00
6.	FRONT DOOR LOCK <i>bt</i>	1	PC	250.00
7.	FRONT DOOR CATCH LH <i>X</i>	1	PC	35.00
8.	REAR DOOR LH <i>bu</i>	1	PC	650.00
9.	REAR DOOR PROTECTOR LH <i>cm</i>	1	PC	80.00
10.	REAR DOOR RUBBER LH <i>ne</i>	1	PC	90.00
11.	REAR DOOR LOWER RUBBER LH <i>ne</i>	1	PC	46.00
12.	REAR DOOR BLACK TAPE LH <i>ne</i>	5	PC	40.00
13.	REAR DOOR LOCK <i>bt</i>	1	PC	260.00
14.	REAR DOOR CATCH <i>X</i>	1	PC	35.00
15.	REAR DOOR OUTER MOULDING LH <i>cm</i>	1	PC	75.00
16.	REAR DOOR HINGE LH <i>bt</i>	2	PC	48.00
17.	REAR FENDER 1/4 GLASS C/W MOULDING LH <i>cut</i>	1	PC	390.00
18.	REAR FENDER 1/4 GLASS SEALANT <i>cm</i>	1	PC	40.00
19.	ROCKER GARNISH LH <i>to</i>	1	PC	390.00
20.	ROCKER GARNISH CLIPS <i>ne</i>	10	PC	5.00
21.	ROCKER PANEL LH <i>repair</i>	1	PC	300.00
22.	ROCKER PANEL TOP GARNISH LH <i>X</i>	2	PC	75.00
23.	CENTRE PILLAR LH <i>bt</i>	1	PC	300.00
24.	CENTRE PILLAR INNER MEMBER LH <i>repair</i>	1	PC	250.00
25.	FLOOR PANEL - REPAIR	1	PC	
26.	REAR FENDER LH - REPAIR	1	PC	

LIST TOTAL S\$

15% COST PLUS S\$

3852.00
577.80
4429.80
40.00 - SN
2040.00 - LB
\$ 6509.80

9 days
=

4,742.00

711.30

5,453.30

LABOUR :

TO CUT & WELD CENTRE PILLAR LH, CENTRE INNER MEMBER LH, ROCKER PANEL LH, TO REPAIR LH FLOOR PANEL, REAR FENDER LH. TO REMOVE & REFIT DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS

TO SPRAY AFFECTED AREAS

TO REMOVE & REFIX DOOR MECHANISM, TRANSFER DOOR POWER WINDOW, CHECK & TEST POWER WINDOW AND CENTRE LOCKING SYSTEM

TO REMOVE & REFIX SAFETY BELT, REAR CUSHION CARPET AND OTHER ATTACHMENT PARTS

TO PROGRAMMING ADAS SYSTEM

TO REMOVE & REFIX ROOF LILING, FRONT CUSHION

900 1,400.00

800 1,200.00

80 160.00

60 120.00

100 200.00